



SKODA OCTAVIA COMBI: GP-138-VF

Vinnumber:	TMBJG8NX9PY158837	Versionname:	SKODA OCTAVIA COMBI 2.0 TDI 116 DSG7 Business	
First Registrationdate:	26/06/2023	Fiscalpower:	VP [5P] bva 7-116CH-6cv (break)	
Expertise Mileage:	185560	Power Kw:	85	
Bodytype:	Break	Body colour:	Black	
Gearbox:	Automatic	Paint type:	Metallic	
Transmission:	Front	Interior colour:	Black	
Fueltype:	Diesel	Type of rims (mounted):	Aluminium	
Engine functioning:	Yes	Dashboard color:	Black	
Battery functioning:	Yes			
Vehicle running:	Yes			
Number of doors:	5			
Number of seats:	5			
Number head rests:	5			
Type of rims (mounted):	Aluminium			
Category:	Passenger Car			

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	205/60/16/92 H			
Summer tyres:	Fr.L.	Continental: 50%	Fr.R.	Continental: 45%
	Re.L.	Hankook: 45%	Re.R.	Hankook: 55%
Tyre profile depth FL				5.0
Tyre profile depth FR				5.1
Tyre profile depth RL				5.4
Tyre profile depth RR				4.7
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Jack	Yes
Remote ignition key (no insert), Missing, Repair/replace (lump sum)	



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



Rear window, Broken, Replace



Bumper R, Bad repair, Paint



Historique Maintenance

Immatriculation: GP-138-VF Date de 1ère immatriculation: 26/06/2023

Modèle: Skoda OCTAVIA COMBI 2.0 TDI 116 DSG7 Business VP [5P] bva 7-116CH-6cv (break)

Date	Kilométrage	Fournisseur	Descriptif
12/06/2026	185.536	ESPACE AUTO ARTIGUES	REVISION ET CLIM ET AIR ET CARBURANT
14/11/2025	151.626	CH DE B	ADBLUE
			REVISION
			LIQUIDE DE FREIN
			DISQUES PLAQUETTES AV RPLT
27/06/2025	126.444	CONTITRADE FRANCE	GARDIENNAGE
			REMPLACEMENT PNEUS ETE
			PERMUTATIONS PNEUS
23/05/2025	122.447	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
			REMPLACEMENT PNEUS ETE
			GARDIENNAGE
25/04/2025	118.982	CH DE B	REVISION ET CLIM
			ADBLUE
			LIQUIDE DE FREIN
			PILE DE CLE RPLT
			BALAIS ESSUIE GLACE AV
12/11/2024	90.247	CH DE B	ADBLUE
			PLAQUETTES AR RPLT
			REVISION ET CLIM ET AIR ET CARBURANT
			PILE DE CLE RPLT
21/10/2024	85.243	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			REMPLACEMENT PNEUS HIVER
			PERMUTATIONS PNEUS
28/06/2024	63.825	CH DE B	BALAIS ESSUIE GLACE AV
			PILE DE CLE RPLT
			REVISION ET CLIM
			ADBLUE
			BALAI ESSUIE GLACE AR
21/06/2024	62.715	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
			GARDIENNAGE
29/01/2024	32.795	CH DE B	PILE DE CLE RPLT

Historique Maintenance

Immatriculation: **GP-138-VF**

Date de 1ère immatriculation: **26/06/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 116 DSG7 Business VP [5P] bva 7-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
			REVISION
17/10/2023	12.768	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
			GARDIENNAGE