MACADAM









CITROÃ‹N BERLINGO: FT-257-BN

Vinnumber:	**VR7EFYHYCLN545355**	Versionname:	**CITROÃ‹N BERLINGO Taille M 650kg BlueHDi 100 S&S BVM Club VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**29/09/2020**	Fiscalpower:	
Expertise Mileage:	**126413**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	**Manual climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Kleber: 70%**	Fr.R.	**Kleber: 70%**
	Re.L.	**Kleber: 60%**	Re.R.	**Kleber: 80%**

Tyre profile depth FL	**3.8**
Tyre profile depth FR	**3.8**
Tyre profile depth RL	**4.2**
Tyre profile depth RR	**2.9**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**195/65 R 15 91 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2479**
Tyre make FR	**2479**
Tyre make RL	**2479**
Tyre make RR	**2479**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Floor mat F, Deformed / Strained, Replace








Dashboard, Unclasped, Dismount/Mount




Armrest F M, Stain, Cleaning




Seat cover FR, Stain, Cleaning




Tyre FR, Out of tolerance, Replace





Tyre RR, Out of tolerance, Replace





Tyre FL, Out of tolerance, Replace





Wing FL, Scratch(es), Acceptable





Door FL, Scratch(es), Paint




Side wall RL, Rust, Paint










Door FR, Dent(s) and scratch(es), Repair and paint (complete)







Side wall RR, Dent(s), Acceptable




Bumper R, Deformed / Strained, Repair and paint (complete)









Boot door panel RL, Scratch(es), Acceptable






Door seal R, Tear, Replace




Load compartment roof, Rust, Paint





