MACADAM









VOLKSWAGEN TOURAN: FH-943-WX

Vinnumber:	**WVGZZZ1TZKW992356**	Versionname:	**VOLKSWAGEN TOURAN 1.6 TDI 115 DSG7 Confortline Bu BMT 7 pl VP [5P] bvm 7-115CH-6cv (mini monospace)**
First Registrationdate:	**16/07/2019**	Fiscalpower:	
Expertise Mileage:	**149229**	Power Kw:	**85**
Bodytype:	**MPV**	Body colour	**Dark Grey**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**7**		
Number head rests	**7**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/60/16/96 H**			
	Fr.L.	**Hankook: 75%**	Fr.R.	**Hankook: 80%**
	Re.L.	**Hankook: 25%**	Re.R.	**Hankook: 30%**

Tyre profile depth FL	**3.3**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**6.4**
Tyre profile depth RR	**6.2**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Interior, Stain, Cleaning







Centre console, Scratch(es), Replace



Armrest F M, Burned, Smart repair



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Alloy rim FR, Scratch(es), Acceptable



Door FL, Dent(s), Repair and paint (complete)



Bumper F, Deformed / Strained, Repair and paint (complete)




Headlight L, Crack, Replace



Door RR, Dent(s), Acceptable



Wing FR, Scratch(es), Polish



Bumper R, Scratch(es), Paint




Boot lid covering R, Scratch(es), Replace





ALPHABET

Historique Maintenance

Immatriculation: **FH-943-WX** Date de 1ère immatriculation: **16/07/2019**

Modèle: **Volkswagen TOURAN 1.6 TDI 115 DSG7 Confortline Bu BMT 7 pl VP [5P] bvm 7-115CH-6cv (mini monospace)**

Date	Kilométrage	Fournisseur	Descriptif
30/06/2026	147.736	VGRF HAUTS-DE-FRANCE RIVERY	LIQUIDE LAVE GLACE
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			REVISION
30/06/2026	147.736	VGRF HAUTS-DE-FRANCE RIVERY	Frais de participation à l'environnement
07/08/2025	134.408	DEKRA AUTOMOTIVE S.A	CONTRE VISITE CT
28/07/2025	133.553	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS 4 SAISONS
21/07/2025	133.385	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
09/07/2025	131.359	VGRF HAUTS-DE-FRANCE RIVERY	DIVERS ELEC
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
12/06/2025	128.341	VGRF HAUTS-DE-FRANCE RIVERY	LIQUIDE DE FREIN
			RECYCLAGE
			LIQUIDE LAVE GLACE
			ADBLUE
			DISQUES PLAQUETTES AR RPLT
			DISQUES PLAQUETTES AV RPLT
			REVISION
11/06/2024	110.629	VGRF HAUTS-DE-FRANCE RIVERY	RECYCLAGE
			REVISION
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			ADBLUE
			LIQUIDE LAVE GLACE
14/03/2024	105.728	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS 4 SAISONS
13/07/2023	94.301	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
01/06/2023	91.457	VGRF HAUTS-DE-FRANCE RIVERY	RECYCLAGE
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV

Historique Maintenance

Immatriculation: **FH-943-WX** Date de 1ère immatriculation: **16/07/2019**

Modèle: **Volkswagen TOURAN 1.6 TDI 115 DSG7 Confortline Bu BMT 7 pl VP [5P] bvm 7-115CH-6cv (mini monospace)**

Date	Kilométrage	Fournisseur	Descriptif
			LIQUIDE DE FREIN
			REVISION ET AIR ET CARBURANT
15/11/2022	85.237	VGRF HAUTS-DE-FRANCE RIVERY	PILE DE CLE RPLT
			RECYCLAGE
13/09/2022	80.158	VGRF HAUTS-DE-FRANCE RIVERY	PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			BATTERIE RPLT
			RECYCLAGE
17/06/2022	73.474	NORAUTO SAS (PRODUIT SPE)	LAMPE CODE AVD RPLT
17/06/2022	73.474	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
18/11/2021	60.676	GARAGE DANIEL SARL	PILE DE CLE RPLT
			REVISION
28/09/2021	56.136	PROFIL PLUS	REMPLACEMENT PNEUS HIVER
06/08/2020	29.383	MACON SPORT AUTOMOBILES	BALAIS ESSUIE GLACE AV AR
			ADBLUE
			REVISION