

MACDAM

Hyundai Ioniq 5 '21 BEV

Vehicle information

Make:	Hyundai	License:	
Gearbox:	Automatic	Body color:	
Model:	Ioniq 5 '21 BEV	VIN:	KMHKN81AFNU032114
Fuel type:	Electric	Power:	160 kW
Version:	IONIQ 5 73kWh RWD Connect+	First registration	08/12/2021
Mileage:	167971 km	N° of doors:	

Damage summary

Front	2
Interior	1
Left	1
Rear	2
Right	4
Roof & others	1

Commercial pictures





Batterijcertificaat

Datum van diagnose: 14/07/2026

97.8%

Status van de gezondheid (SOH)*

Hyundai Ioniq Elec.


VIN : KMHKN81AFNU032114
Kilometerstand : 167.971 km

*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

Meer weten op:
www.get-moba.com

CARA
Aspirant Battery Health Check



Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Rear view camera	Yes	Telephone equipment
Yes				Yes
Yes				Yes
Damages				
Bonnet Chemical polution Repair and paint (complete) Front  				
Boot lid covering R Scratch(es) Smart repair Rear  				
Bumper corner RR Scratch(es) Repair and paint (complete) Rear  				
Door FR Bad repair Repair and paint (complete) Right  				
Door RL Scratch(es) Repair and paint (complete) Left  				



Door RR
Bad repair
Repair and paint (complete)
Right



Interior
Not original part
Replace
Interior



Roof
Dent(s)
Paintless dent repair
Roof & others



Wheel arch cover FR
Broken
Replace
Right



Windscreen

Crack
Replace
Front



Wing RR

Bad repair
Repair and paint (complete)
Right



Tyres

Front Left

Summer

235/55/19/105/W

Michelin

6.7 mm

Front Right

Summer

235/55/19/105/W

Michelin

6.3 mm

Rear Left

Summer

235/55/19/105/W

Michelin

4.1 mm

Rear Right

Summer

235/55/19/105/W

Michelin

5.6 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	Yes	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.