# VEHICLE REPORT

IT · 11/11/2026
2026-11-11 14:49

VIN: Targa: Merchant:

## VEHICLE DETAILS

| | | | |
|---|---|---|---|
| Targa | | First Registration | **2015-07-31** |
| Marca | N/A | Mileage | N/A |
| Modello e Allestimento | | Keys | N/A |
| VIN | | Owners | **2** |
| Merchant | | Seats | **5** |
| Branch | | Previous Use | **AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE** |
| KW | **193** | VAT | N/A |
| CC | **0** | Country | **IT** |
| Fuel | **GASOL** | Euro | **EURO6** |
| GPL | **Non presente** | Cambio | **Non presente** |
| Gancio | N/A | | |

## CAR PHOTOS (51)


*Trunk*



*Speedometer with started engine*


*Speedometer with started engine*


*Interior front*


*Interior front*


*Interior front*


*Center console and dashboard*


*Interior front*


*Interior rear*


*Trunk*


*Trunk*


*Interior front*


*Interior rear*


*Interior front*


*Roof*


*Interior rear*


*Interior front.*


*Speedometer with started engine*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Trunk*


*Rear fender left*


*Left side front*


*Additional photos (optional)*


*Trunk*


*Front left*


*Right side rear*



Rear



Left side rear



Front left



Front



Front left



Interior front.



Interior rear



Trunk



Front door left



Roof.



Additional photos (optional)



Front door left



Rear fender left



Rear fender right



Hood



Additional photos (optional)



Left side front



Engine compartment



Engine compartment



Rear fender left



Rear fender left