

MACDAM

Peugeot * Partner '18

Vehicle information

Make:	Peugeot	License:	
Gearbox:	MAN 5 VIT	Body color:	
Model:	* Partner '18	VIN:	VR3EFBHYBKN523872
Fuel type:	Diesel	Power:	73 kW
Version:	Part.1.6HDi 100 L1 H Prem.1000	First registration	28/06/2019
Mileage:	127863 km	N° of doors:	

Damage summary

Front	1
Interior	2
Left	1
Rear	3
Right	1
Roof & others	1

Commercial pictures





Options according to the inspector

Central consol F	Yes	Radio multimedia	Yes	Telephone equipment	Yes
------------------	-----	------------------	-----	---------------------	-----

Damages

Armrest F M
 Damaged
 Replace
 Interior



Bodywork

Not original part
Remove lettering
Roof & others



Boot door panel RL

Dent(s) and scratch(es)
Repair and paint (complete)
Rear



Bumper corner RL

Scratch(es)
Replace
Rear



Bumper F

Scratch(es)
Smart repair
Front



Bumper R
Scratch(es)
Smart repair
Rear



Door FR
Dent(s)
Repair and paint (complete)
Right



Interior
Stain
Cleaning
Interior



Wing RL
Dent(s)
Repair and paint (complete)
Left



Tyres

Front Left

Summer

205/60/16/96/H

Continental

6.2 mm

Front Right

Summer

205/60/16/96/H

Continental

6.2 mm

Rear Left

Summer

205/60/16/96/H

Continental

7.1 mm

Rear Right

Summer

205/60/16/96/H

Continental

7.1 mm

Checks

CO2 Emission	109	Digital maintenance	N/A
GPS storage	N/A	Luggage cover	N/A
Number head rests	2	Number of keys total	2
Reset to factory settings	Yes, vehicle is reset to factory settings	Service book	Yes
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.