



PEUGEOT 308: FX-431-TN

Vinnumber:	VF3LBYHZKMS074093	Versionname:	PEUGEOT 308 BlueHdi 130 EAT8 S&S ALLURE PACK VP [5P] bva 8-130CH-7cv (bi-corps)
First Registrationdate:	11/03/2021	Fiscalpower:	
Expertise Mileage:	147720	Power Kw:	96
Bodytype:	Berline	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Semi-leather
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Other: 45%	Fr.R.	Other: 45%
	Re.L.	Bridgestone: 55%	Re.R.	Bridgestone: 55%
Tyre profile depth FL				5.3
Tyre profile depth FR				5.3
Tyre profile depth RL				4.6
Tyre profile depth RR				4.6
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key (no insert), Missing, Repair/replace (lump sum)			



Interior, Stain, Cleaning



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Paint



Outside rear-view mirror housing L, Scratch(es), Paint



Door RL, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)

