



**RENAULT CLIO: GF-968-DQ**

Vinnumber:	<b>VF1RJA00169054873</b>	Versionname:	<b>RENAULT CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)</b>
First Registrationdate:	<b>11/03/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>99623</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Berline</b>	Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Grey</b>
Fueltype:	<b>Petrol</b>	Type of rims (mounted):	<b>Steel</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Category:	<b>Passenger Car</b>		

**Options**

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	<b>Lining Other</b>
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Manual climate control</b>		

**Tyres**

<b>195/55/16/87 H</b>				
Summer tyres:	Fr.L.	<b>Hankook: 70%</b>	Fr.R.	<b>Hankook: 70%</b>
	Re.L.	<b>Kleber: 45%</b>	Re.R.	<b>Kleber: 45%</b>
Tyre profile depth FL				<b>3.8</b>
Tyre profile depth FR				<b>3.8</b>
Tyre profile depth RL				<b>5.4</b>
Tyre profile depth RR				<b>5.2</b>
Tyre size FL				<b>195/55 R 16 87 H</b>
Tyre size FR				<b>195/55 R 16 87 H</b>
Tyre size RL				<b>195/55 R 16 87 V</b>
Tyre size RR				<b>195/55 R 16 87 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>260</b>
Tyre make FR				<b>260</b>
Tyre make RL				<b>2479</b>
Tyre make RR				<b>2479</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Remote ignition key, Missing, Repair/replace (lump sum)			



**Interior, Stain, Cleaning**



Floor mat F, Tear, Replace



Tyre FL, Out of tolerance, Replace



Wheel cover FL, Deformed / Strained, Replace



Tyre FR, Out of tolerance, Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Door RL, Scratch(es), Paint



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Dent(s), Repair and paint (complete)



Headlight L, Scratch(es), Replace



Bumper F, Crack, Repair and paint (complete)



Bumper grille, Scratch(es), Replace



Grille, Broken, Replace



Grille, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Replace



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Scratch(es), Replace



Door trim RR, Scratch(es), Replace



Door RR, Scratch(es), Polish



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Luggage cover stopper, Missing, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper spoiler Rear, Scratch(es), Repair and paint (complete)



Bodywork, Not original part, Sticker removal small



# Historique Maintenance

Immatriculation: **GF-968-DQ**Date de 1ère immatriculation: **11/03/2022**Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
14/05/2025	73.522	RENAULT RETAIL GROUP	REVISION ET CLIM
	0		RECYCLAGE
	0		LIQUIDE DE FREIN
30/05/2024	49.037	RENAULT RETAIL GROUP	BALAI ESSUIE GLACE AR
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		BALAI ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
	0		LAMPE RPLT
	0		RECYCLAGE
01/06/2023	27.112	RENAULT RETAIL GROUP	RECYCLAGE
	0		PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		BALAI ESSUIE GLACE AR