



RENAULT CLIO: GD-281-EM

Vinnumber:	VF1RJA00468305648	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	26/11/2021	Fiscalpower:	
Expertise Mileage:	126460	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/91 V			
Summer tyres:	Fr.L.	Hankook: 75%	Fr.R.	Hankook: 75%
	Re.L.	Uniroyal: 35%	Re.R.	Uniroyal: 25%
Tyre profile depth FL				3.5
Tyre profile depth FR				3.5
Tyre profile depth RL				6.0
Tyre profile depth RR				6.5
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Armrest F M, Broken, Replace



Wheel cover FR, Broken, Replace



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Door water strip FL, Missing, Replace



Bumper F, Scratch(es), Paint



Wing FR, Dent(s) and scratch(es), Replace and paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Rear light R tailgate, Broken, Replace



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: **GD-281-EM** Date de 1ère immatriculation: **26/11/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
13/05/2026	124.295	ADP CHAMPIGNY CHAMPIGNY SUR MARNE	DIVERS MOTEUR
			DIAG
26/02/2026	123.876	GARAGE HARDY AUTOMOBILES	SERENITE
			FILTRE A AIR RPLT
			BOITIER D ALLUMAGE RPLT
24/02/2026	123.873	GARAGE HARDY AUTOMOBILES	LIQUIDE DE FREIN
			DIVERS ECHAPPEMENT
			BOBINES ALLUMAGE RPLT
			DIVERS ELEC
27/11/2024	95.241	GARAGE LE VILLAGE	DIAG
			REVISION ET CLIM
			DIVERS ALIMENTATION
			DIVERS ELEC
			DIVERS ALIMENTATION
			DIVERS ELEC
			JAUGE A CARBURANT RPLT
17/08/2024	90.916	EUROFLEET TYRES AND SERVICES	DIVERS MOTEUR
			RECYCLAGE
			REPLACEMENT PNEUS ETE
			REPLACEMENT PNEUS ETE
23/10/2023	64.106	GUEUDET ALLIANCE OISE	RECYCLAGE
			REVISION ET CLIM ET AIR ET BOUGIES
			DISQUES PLAQUETTES AV RPLT
			PILE DE CLE RPLT
20/10/2023	63.857	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS 4 SAISONS
24/01/2023	34.125	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
10/01/2023	31.764	GUEUDET ALLIANCE OISE	BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			REVISION