



**Mercedes-Benz A180: R788ZH**

Vinnumber:	<b>W1K3F8EB2PV160114</b>	Versionname:	<b>A180 1.3 100kW AMG Line DCT</b>
First Registrationdate:	<b>29/12/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>66310</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Mountaingrijs metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>835</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Rear parking sensors
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 18 / 91 / W / Aluminium	5,0 mm	Continental	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	4,3 mm	Continental	Summer
Rear	Left	225 / 45 / 18 / 91 / W / Aluminium	5,2 mm	Continental	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	5,2 mm	Continental	Summer

**Assistance equipment**

Number of charging cables (rapid charge)	<b>0</b>
--	----------

**Bumper F, Bad repair, Repair and paint (complete)**



**Door RR, Dent(s) and scratch(es), Repair and paint (complete)**



**Wing RR, Scratch(es), Polish**



**Roof pillar R, Scratch(es), Repair and paint (complete)**



<b>Kenteken</b>	R788ZH
<b>Merk Model</b>	Mercedes-Benz A180 1.3 100kW AMG Line DCT
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	29-12-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-03-26	60.664	Bougie
09-03-26	60.664	Luchtfilter
09-03-26	60.664	Onderhoudsbeurt
09-03-26	60.664	Ruitenwischerblad(en) voorzijde
10-12-25	56.193	Boordcomputer
17-02-25	40.838	Onderhoudsbeurt
17-02-25	40.838	Remvloeistof
17-02-25	40.838	Ruitenwischerblad(en) achterzijde
17-02-25	40.838	Ruitenwischerblad(en) voorzijde
26-01-24	18.104	Onderhoudsbeurt
26-01-24	18.104	Ruitenwischerblad(en) voorzijde
10-10-23	11.673	Reparatie band(en)