



HYUNDAI TUCSON: GM-278-NG

Vinnumber:	TMAJC811BPJ165625	Versionname:	HYUNDAI TUCSON 1.6 HYBRID 230 BUSINESS VP
First Registrationdate:	6/03/2023	Fiscalpower:	[5P] bva 6-230CH-10cv (SUV)
Expertise Mileage:	88546	Power Kw:	169
Bodytype:	Off-road	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

	215/65/17/99 V			
Summer tyres:	Fr.L.	Hankook: 30%	Fr.R.	Hankook: 30%
	Re.L.	Michelin: 35%	Re.R.	Michelin: 40%
Tyre profile depth FL				6.1
Tyre profile depth FR				6.2
Tyre profile depth RL				5.8
Tyre profile depth RR				5.6
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Jack	Yes
------	------------

Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning



Seat cover FL, Stain, Cleaning



Armrest RM, Scratch(es), Repair/replace (lump sum)



Door panel RR, Scratch(es), Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Paint



Wing trim FL, Scratch(es), Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Bumper F, Deformed / Strained, Replace and paint



Bumper moulding F, Deformed / Strained, Replace and paint



Door FR, Dent(s), Repair and paint (complete)



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Bumper corner RL, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GM-278-NG** Date de 1ère immatriculation: **06/03/2023**

Modèle: **Hyundai TUCSON 1.6 HYBRID 230 BUSINESS VP [5P] bva 6-230CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
07/04/2026	81.595	PARK LANN AUTOMOBILES	BOUGIES ALLUMAGE RPLT
	0		REVISION
13/08/2025	65.577	PARK LANN AUTOMOBILES	LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
14/08/2025	64.419	PROFIL PLUS	REPLACEMENT PNEUS 4 SAISONS
27/01/2025	53.106	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
06/01/2025	50.618	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
24/10/2024	47.277	AUTO NORD	REVISION
02/09/2024	47.224	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
02/09/2024	47.224	CONTITRADE FRANCE	REPARATION DE ROUE
08/03/2024	31.996	AUTOMOBILES DELAHAYE	FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
10/01/2024	27.498	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
18/10/2023	18.804	AUTOMOBILES DELAHAYE	REVISION