



BMW 1 Reeks (UKL): 2BVK521

Vinnumber:	WBA7M710807K91118	Versionname:	116d (F40) 1.5d 116pk/cv 5p
First Registrationdate:	6/04/2022	Fiscalpower:	
Expertise Mileage:	27326	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	over 19000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/94 H			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 94 H
Tyre size FR				205/55 R 16 94 H
Tyre size RL				205/55 R 16 94 H
Tyre size RR				205/55 R 16 94 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	No
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Ignition key, Not functioning (well), Acceptable



Backrest cover FR, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Tyre repair kit, Missing, Check



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Bad repair, Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Outside rear-view mirror base R, Scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Roof, Chemical polution, Acceptable



Kenteken	2BVK521
Merk Model	BMW 116d (F40) 1.5d 116pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	4/6/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/4/26	23,130	batterij	Vervangen
3/4/26	23,130	BMW/MINI service standaard omvang	Uitvoeren
3/4/26	23,130	BMW/MINI service voertuig-check	Uitvoeren
3/4/26	23,130	koelwatervloeistof	Bijvullen/-laden
3/4/26	23,130	ruitenwisserrubber achter	Vervangen
3/4/26	23,130	ruitenwisserrubber vooraan	Vervangen
3/4/26	23,130	ruitenwisservloeistof	Bijvullen/-laden
3/4/26	23,130	service brandstoffilter	Uitvoeren
3/4/26	23,130	service luchtfilter	Uitvoeren
3/4/26	23,130	service microfilter	Uitvoeren
3/4/26	23,130	service motorolie	Uitvoeren
6/19/25	15,470	BMW/MINI service standaard omvang	Uitvoeren
6/19/25	15,470	controle niveaus	Uitvoeren
6/19/25	15,470	remvloeistof	Vervangen
4/17/24	5,979	batterij	Vervangen
4/17/24	5,979	BMW/MINI service standaard omvang	Uitvoeren
4/17/24	5,979	ruitenwisserrubber achter	Vervangen
4/17/24	5,979	ruitenwisserrubber vooraan	Vervangen
4/17/24	5,979	service microfilter	Uitvoeren
4/17/24	5,979	service motorolie	Uitvoeren