MACADAM










Polestar 2: P125KV

Vinnumber:	**LPSVSEGEKNL067428**	Versionname:	**Polestar 2 170kW/ 78kWh Single Motor Long Range**
First Registrationdate:	**29/04/2022**	Fiscalpower:	
Expertise Mileage:	**155535**	Power Kw:	**170**
Bodytype:		Body colour	**zwart**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1037**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / Y / Aluminium	4,4 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	5,2 mm	Michelin	Summer
Rear	Left	245 / 45 / 19 / 102 / Y / Aluminium	4,3 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	2,6 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Full-screen GPS, Not functioning (well), Replace



Wing FL, Stone chip(s), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)






Door RL, Scratch(es), Repair and paint (complete)




Bonnet, Stone chip(s), Repair and paint (complete)





Door FR, Bad repair, Repair and paint (complete)




Wing RR, Stone chip(s), Repair and paint (complete)





Door RR, Scratch(es), Repair and paint (complete)




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)






Onderhoudshistorie van: LPSVSEGEKNL067428

ALPHABET

Kenteken	P125KV
Merk Model	Polestar Polestar 2 170kW/ 78kWh Single Motor Long Range
Brandstofsoort	Elektrisch
Datum deel1	4/29/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/9/26	140,805	APK
8/28/25	125,579	Airo vulling
8/28/25	125,579	Onderhoudsbeurt
8/28/25	125,579	Remvloeistof
9/20/24	95,027	Onderhoudsbeurt
9/20/24	95,027	Reparatie band(en)
9/20/24	95,027	Ruitenwisserblad(en) voorzijde
9/20/24	95,027	Uitlijnen voor en achterwielen
7/9/24	88,730	Reparatie band(en)
1/2/24	64,544	Onderhoudsbeurt
6/10/22	3,934	Vervanging band