




VOLVO V60:				
Vinnumber:	YV12WK6VDM2436262	Versionname:	B3 Geartronic Momentum Core	
First Registrationdate:	20/01/2021	Fiscalpower:		
Expertise Mileage:	177373	Power Kw:	120	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3807	
Fueltype:	Hybrid Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	No Tow bar	
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/50/17/99 V			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 17 99 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/50 R 17 98 V
Tyre size RR				225/50 R 17 98 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1570,68
Interior, Dirty, Cleaning				175,04



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door RL, Repaired, Acceptable	0,00
-------------------------------	------



Door FL, Scratch(es), Repair and paint (complete)

445,79



Rubber seal for boot lid, Broken, Replace

117,50



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Rear window, Scratch(es), Replace

535,77



Alloy rim FR, Scratch(es), Acceptable

0,00



Sill trim R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00

