



Peugeot Partner: V22FVL

Vinnumber:	VR3EDYHT5RJ666977	Versionname:	Partner 1.5 BlueHdi 75kW S&S 1000kg L2
First Registrationdate:	14/06/2024	Fiscalpower:	
Expertise Mileage:	90347	Power Kw:	75
Bodytype:		Body colour	Wit (Kaolin White)
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Diesel	Parking lot	738
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	Yes		

Options

Number of keys total	1	Rear parking sensors
Manual climate control		Sliding door right-side
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 96 / V / Steel	5,2 mm	Bridgestone	All season
	Right	205 / 60 / 16 / 96 / V / Steel	4,4 mm	Bridgestone	All season
Rear	Left	205 / 60 / 16 / 96 / V / Steel	4,4 mm	Bridgestone	All season
	Right	205 / 60 / 16 / 96 / V / Steel	7,1 mm	Bridgestone	All season

Assistance equipment

Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Outer sill R, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Roof, Chemical polution, Repair and paint (complete)



Kenteken	V22FVL
Merk Model	Peugeot Partner 1.5 BlueHDi 75kW S&S 1000kg L2
Brandstofsoort	Diesel
Datum deel1	14-06-24

Datum reparatie	Kilometerstand	Reparatie omschrijving
21-05-26	83.156	Reparatie band(en)
21-05-26	83.156	Vervanging band
11-03-26	75.507	Onderhoudsbeurt
14-11-25	63.441	Brandstoffilter
14-11-25	63.441	Luchtfilter
14-11-25	63.441	Onderhoudsbeurt
19-09-25	57.390	Reparatie band(en)
19-09-25	57.390	Vervanging band
10-07-25	47.167	Onderhoudsbeurt
21-03-25	32.856	Brandstoffilter
21-03-25	32.856	Luchtfilter
21-03-25	32.856	Onderhoudsbeurt
21-03-25	32.856	Reparatie band(en)
21-03-25	32.856	Ruitenwisserblad(en) voorzijde
05-02-25	26.592	Reparatie band(en)
06-12-24	17.744	Onderhoudsbeurt
19-06-24	2	Vervanging band