

### Vehicle details

VIN	VF1RFK009 72254837	Brand	RENAULT	Maintenance date	-
Licence Plate	[Redacted]	Model	KANGOO Blue dCi 75 Comfort 4d	Maintenance mileage	-
Registration date	16/07/2024	Year	2024	Exterior Color	White Solid
Odometer	196 763 km	Engine size	1461	Interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	6		

### Inspection Details

Inspection date 19/05/2026

### Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

### Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

### Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

### Tyres

Front Left: Michelin 205/60/16 All seasons 4.0 mm




Front Right: Michelin 205/60/16 All seasons 4.0 mm

Rear Left: Michelin 205/60/16 All seasons 5.0 mm



Rear Right: Michelin 205/60/16 All seasons 4.0 mm

### Exterior

3		Part	Additional headlights	4		Part	Side panel
		Position	-			Position	Back left
		Damages	Not conform			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>6</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Tipper body</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Clear</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Tipper body	Position	-	Damages	Clear	Severity	-	Repair mode	For info
Part	Door																						
Position	Front right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Tipper body																						
Position	-																						
Damages	Clear																						
Severity	-																						
Repair mode	For info																						
<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	-	Repair mode	Repair												
Part	Bumper																						
Position	Front																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						

### Interior damage

<p>1</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning		
Part	Interior cleaning												
Position	-												
Damages	Stained/dirty												
Severity	-												
Repair mode	Cleaning												
<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Fabric seat</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Worn out</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Fabric seat	Position	Front left	Damages	Worn out	Severity	-	Repair mode	For info		
Part	Fabric seat												
Position	Front left												
Damages	Worn out												
Severity	-												
Repair mode	For info												