



Vehicle History Report

MERCEDES GLE 350 de 4MATIC

Vehicle reference:

W1N1673171A562658

Body type:
Estate

Gearbox
type:
Automatic

Engine size:
1950 cm³

Hybrid
vehicle:
Electric,
Diesel

Combustion
engine
power:
143 kW /
194 hp

Drive:
AWD

Located in Italy



Vehicle age

**4 years
1 month**

How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



Quick Check

Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

● **Damage**

Import

Not a private import

● **No issues reported**

Damage Overview

2023-03-23 Damage reported



Damage type/cause:
Collision with another vehicle

Reported on:
2023-03-23

Reported in:
Italy

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

Owners **BETA**



Owner(s) in Italy

Purchase year: **2021**

Damage reported on: **2023-03-23**

History information

Date	Event
2021-12-10	Registered in Italy
2023-03-23	Damage reported in Italy

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Engine and performance	
Hybrid vehicle	Electric, Diesel
Combustion engine power	143 kW / 194 hp
Electric engine power	Not available
Total system power	Not available
Environment and consumption	
EU emission standard	Euro 6
Weight	
Curb weight	2 690 kg
Max payload	540 kg
Gross vehicle weight	3 230 kg
Dimensions	
Length	4 961 mm
Width	2 014 mm
Wheelbase	2 935 mm
Other information	
European vehicle category	M1
EU standard code	e1*2007/46*1885*13
Number of doors	5
Number of seats	5

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.