



CITROËN BERLINGO: EW-343-LG

Vinnumber:	VF77DBHY6JJ595485	Versionname:	CITROËN BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)
First Registrationdate:	9/04/2018	Fiscalpower:	
Expertise Mileage:	116893	Power Kw:	73
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	3		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	2	Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

195/65/15/91 T				
Winter tyres:	Fr.L.	Michelin: 50%	Fr.R.	Michelin: 50%
	Re.L.	Bridgestone: 40%	Re.R.	Bridgestone: 40%
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.5
Tyre profile depth RR				5.5
Tyre size FL				195/65 R 15 91 T
Tyre size FR				195/65 R 15 91 T
Tyre size RL				195/65 R 15 91 T
Tyre size RR				195/65 R 15 91 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			





Door seal FL, Tear, Replace



Air vent, mid-dashboard, Damaged, Replace



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Outer sill L, Scratch(es), Paint



Bumper moulding FL, Broken, Replace



Outside rear-view mirror base R, Broken, Replace



Door FR, Scratch(es), Paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Not original part, Acceptable



Historique Maintenance

Immatriculation: **EW-343-LG** Date de 1ère immatriculation: **09/04/2018**

Modèle: **Citroen BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
25/02/2026	116.804	DMDA	DIVERS CARROSSERIE
	0		EMBRAYAGE RPLT
	0		AMORTISSEURS AV RPLT
	0		DIVERS DIRECTION
	0		DIVERS
	0		RECEPTEUR EMBRAYAGE RPLT
10/12/2024	113.783	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS HIVER
03/12/2024	113.288	MICHON	DIAG
	0		SERRURE DE PORTE ARD RPLT
12/11/2024	111.317	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
26/09/2024	111.250	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
03/05/2024	110.964	GARAGE VAISSAUD	DIVERS ECHAPPEMENT
	0		ECLAIRAGE DE PLAQUE RPLT
	0		CONTROLE TECHNIQUE
	0		LAMPE RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		SOUFFLET DE CARDAN RPLT
12/03/2024	108.659	GARAGE VAISSAUD	LAMPE AR RPLT
	0		LAMPE RPLT
	0		DIAG
03/01/2024	105.422	GARAGE VAISSAUD	LAMPE AR RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		ADBLUE
	0		ECLAIRAGE DE PLAQUE RPLT
09/11/2023	103.598	GARAGE VAISSAUD	APPOINT D HUILE
28/06/2023	99.953	CONTITRADE FRANCE	PERMUTATIONS PNEUS
31/03/2023	95.188	DEKRA AUTOMOTIVE S.A	ANTIPOLLUTION
11/01/2023	92.810	GARAGE VAISSAUD	LAMPE CODE AVD RPLT
06/12/2022	90.545	GARAGE VAISSAUD	LIQUIDE DE FREIN
	0		DIVERS CLIM

Historique Maintenance

Immatriculation: **EW-343-LG**

Date de 1ère immatriculation: **09/04/2018**

Modèle: **Citroen BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		ADBLUE
	0		BALAI ESSUIE GLACE AR
06/12/2022	90.545	GARAGE VAISSAUD	REPARATION DE ROUE
25/11/2022	90.230	CONTITRADE FRANCE	PERMUTATIONS PNEUS
30/05/2022	79.275	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
20/04/2022	77.339	GARAGE VAISSAUD	PLAQUETTES AR RPLT
	0		SOUFFLET DE CARDAN RPLT
	0		CONTROLE TECHNIQUE
	0		APPOINT D HUILE
	0		LAMPE AR RPLT
	0		LAMPE RPLT
23/11/2021	68.139	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
10/11/2021	67.463	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
28/09/2021	64.265	GARAGE VAISSAUD	ADBLUE
	0		REVISION
	0		LAMPE AR RPLT
01/04/2021	55.526	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
05/10/2020	43.943	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
14/09/2020	43.811	GARAGE VAISSAUD	BATTERIE RPLT
	0		LAMPE RPLT
	0		PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		ADBLUE
16/09/2019	28.750	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
	0		REMPLACEMENT PNEUS HIVER
27/08/2019	23.014	GARAGE VAISSAUD	DIVERS ECHAPPEMENT
12/06/2019	23.014	GARAGE VAISSAUD	ADBLUE
	0		FEU ARG RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
29/01/2019	13.519	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
07/01/2019	11.383	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER