MACADAM











Toyota Corolla (UKL): 2CRH907

Vinnumber:	**SB1Z93BE90E331934**	Versionname:	**Corolla Touring Sports Dynamic 1.8i Hybrid 122pk/cv 5p eCVT**
First Registrationdate:	**27/10/2022**	Fiscalpower:	
Expertise Mileage:	**58726**	Power Kw:	**72**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**geen melding**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar removable**
Type of Maintenance book	**Maintenance book present**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Continental: 3 mm**	Fr.R.	**Continental: 3 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

MOT certificate, Non-conforme, Replace



Seat cover FR, Stain, Cleaning









Seat cover R, Stain, Cleaning









Bumper F, Scratch(es), Repair and paint (complete)















Bumper R, Scratch(es), Spot repair




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)








Door RR, Dent(s) and scratch(es), Repair and paint (complete)










Alloy rim FR, Scratch(es), Repair and paint (complete)






Onderhoudshistorie van: SB1Z93BE90E331934

ALPHABET

Kenteken	2CRH907
Merk Model	Toyota Corolla Touring Sports Dynamic 1.8i Hybrid 140pk/cv 5p eCVT
Brandstofsoort	Benzine
Datum deel1	10/27/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/25/25	45,392	45000 km	Uitvoeren
11/25/25	45,392	oliezeef	Vervangen
11/27/24	31,160	30000 km	Uitvoeren
11/27/24	31,160	luchtfilter	Vervangen
11/27/24	31,160	luchtfilter interieur	Vervangen
11/27/24	31,160	oliezeef	Vervangen
11/27/24	31,160	ruitenwisserrubber achter	Vervangen
11/27/24	31,160	ruitenwisserrubber vooraan	Vervangen
2/14/24	18,121	15000 km	Uitvoeren
2/14/24	18,121	luchtfilter interieur	Vervangen
2/14/24	18,121	oliezeef	Vervangen