



OPEL CROSSLAND: GH-933-MB

Vinnumber:	W0V7H9EB4N4280890	Versionname:	OPEL CROSSLAND 1.2 Turbo 130ch Auto Elegance Business VP [5P] bva 6-131CH-7cv (SUV)
First Registrationdate:	11/07/2022	Fiscalpower:	
Expertise Mileage:	69311	Power Kw:	96
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Rear view camera	
Windows electric F		Seat cover lining	Lining Other
Windows electric R			Lining Leather
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/60/16/93 H			
Winter tyres:	Fr.L.	Bridgestone: 65%	Fr.R.	Bridgestone: 70%
	Re.L.	Bridgestone: 60%	Re.R.	Bridgestone: 60%
Tyre profile depth FL				4.0
Tyre profile depth FR				3.8
Tyre profile depth RL				4.4
Tyre profile depth RR				4.2
Tyre size FL				195/60 R 16 93 H
Tyre size FR				195/60 R 16 93 H
Tyre size RL				195/60 R 16 93 H
Tyre size RR				195/60 R 16 93 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Seat cover FR, Dirty, Cleaning



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyres, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing trim FL, Scratch(es), Replace



Bumper spoiler F, Scratch(es), Replace



Bumper F, Scratch(es), Acceptable



Door FR, Dent(s), Repair and paint (complete)



Rubber seal for boot lid, Tear, Replace



Bumper R, Scratch(es), Acceptable



Historique Maintenance

Immatriculation: **GH-933-MB** Date de 1ère immatriculation: **11/07/2022**

Modèle: **Opel CROSSLAND 1.2 Turbo 130ch Auto Elegance Business VP [5P] bva 6-131CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
25/11/2025	55.203	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
03/10/2025	54.410	OPL BYMYCAR	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
22/09/2025	53.612	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
28/04/2025	45.090	OPL BYMYCAR	TRIANGLE INFERIEUR AVD RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		DIVERS MOTEUR
16/04/2025	44.848	OPL BYMYCAR	DEMARREUR RPLT
05/11/2024	34.376	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		REPLACEMENT PNEUS HIVER
17/09/2024	34.141	OPL BYMYCAR	DIVERS MOTEUR
06/09/2024	33.872	OPL BYMYCAR	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
	0		TELECHARGEMENT CALCULATEUR
	0		LIQUIDE DE FREIN
27/05/2024	28.036	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
07/11/2023	19.587	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
23/08/2023	17.115		REVISION
02/05/2023	10.289	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
02/12/2022	5.922	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER