


## Vehicle details

|                   |                    |              |                                     |                           |                      |
|-------------------|--------------------|--------------|-------------------------------------|---------------------------|----------------------|
| VIN               | WV1ZZZ7HZ LH030607 | Brand        | VOLKSWAGEN                          | Maintenance date          | -                    |
| Licence Plate     |                    | Model        | TRANSPORTER 2.0TDI 110kW 7-DSG L2H1 | Maintenance mileage       | -                    |
| Registration date | 17/04/2020         | Year         | 2020                                | Exterior Color            | Deep Black Perleffek |
| Odometer          | 184 658 km         | Engine size  | 1968                                | Interior Color            | Unknown              |
| Fuel              | Diesel             | Body Type    | Panel van                           | Next technical inspection | -                    |
| Seats             | 2                  | Transmission | Automatic                           | CO2                       | -                    |
| Doors             | 4                  | Gears        | -                                   |                           |                      |



### Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| GPS system              | ✓ |
| Automatic Gearbox       | ✓ |
| Tow                     | ✓ |
| Metallic paint          | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |


### Removable element

|                            |   |
|----------------------------|---|
| Spare wheel (wheel & tyre) | ✓ |
|----------------------------|---|

### Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres



## Exterior

1



|             |                    |
|-------------|--------------------|
| Part        | Roof post A/B/C    |
| Position    | Left               |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

3



|             |                      |
|-------------|----------------------|
| Part        | Tailgate / Boot door |
| Position    | -                    |
| Damages     | Scratched            |
| Severity    | -                    |
| Repair mode | For info             |

4



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back right         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

5



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

6



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Back left          |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

## Interior damage

2



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Back                     |
| Damages     | Broken                   |
| Severity    | -                        |
| Repair mode | For info                 |