



## PEUGEOT 308 3

VIN	VR3FPHNSTPY651287
Première immatriculation	10/11/2023

### DÉTAILS DE L'INSPECTION

Date de l'inspection 30/04/2026 17:03:36

### INFORMATIONS SUR LE VÉHICULE

VIN	VR3FPHNSTPY651287	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	10/11/2023	Couleur intérieur	Noir
Type de carburant	Essence	Couleur carrosserie	Noir
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

### DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Certificat immatriculation (original)	Non
Nbre clés total	2	Certificat immatriculation (original)	Original
Nbre clés télécommandes	2	Entretien	Oui
Manuel d'utilisation	Oui		

### OPTIONS

Camera de recul	Oui	Nature de peinture	Metallisé
-----------------	-----	--------------------	-----------

## DAMAGES

### Interior



#### 1 | Seat cover FR

Damage type	Stain
Repair mode	Cleaning



#### 2 | Glove compartment lid

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



### Exterior



#### 3 | Tyre FR

Damage type	Out of tolerance
Repair mode	Replace



#### 4 | Tyre FL

Damage type	Out of tolerance
Repair mode	Replace



## 5 | Alloy rim FL bitone/polychrome

Damage type

Scratch(es)

Repair mode

Repair/replace (lump sum)




## 6 | Alloy rim RR bitone/polychrome

Damage type

Scratch(es)

Repair mode

Repair/replace (lump sum)





## 7 | Alloy rim FR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



## 8 | Headlight R

Damage type	Scratch(es)
Repair mode	Polish



## 9 | Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



## 10 | Outside rear-view mirror base R

Damage type	Scratch(es)
Repair mode	Repair and paint (complete)



### 11 | Side repeater R

Damage type	Scratch(es)
Repair mode	Replace



### 12 | Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Polish



### 13 | Bumper R


Damage type	Scratch(es)
Repair mode	Paint





## 14 | Bumper spoiler Rear

Damage type	Scratch(es)
Repair mode	Paint






## 15 | Bodywork

Damage type	Hail damage
Repair mode	Forfeit hail (heavy)







## Commercial photos

