MACADAM








OPEL Grandland PHEV: 7299-MCK

Vinnumber:	**W0VZ4DGZ3N6829677**	Versionname:	**1.6 Turbo PHEV GS Line Auto 165kW/225CV todoterreno 165kW 5P automática**
First Registrationdate:	**24/11/2022**	Fiscalpower:	
Expertise Mileage:	**79391**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Plug-in hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Roof bar black	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/102 V**			
	Fr.L.	**Cooper: 5 mm**	Fr.R.	**Cooper: 5 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/55 R 18 102 V**
Tyre size FR	**225/55 R 18 102 V**
Tyre size RL	**225/55 R 18 102 V**
Tyre size RR	**225/55 R 18 102 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**1957075**
Tyre make FR	**1957075**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**1**		

Boot lid covering R, Scratch(es), Repair/replace (lump sum)




Interior covering A pillar L, Scratch(es), Repair/replace (lump sum)




Door FL, Dent(s), Repair and paint (complete)




Door RL, Dent(s), Repair and paint (complete)




Fender moulding RL, Scratch(es), Repair and paint (complete)




Bonnet, Scratch(es), Repair and paint (complete)




Fender moulding RR, Scratch(es), Repair and paint (complete)




Door RR, Dent(s), Repair and paint (complete)




Bumper spoiler Rear, Dent(s) and scratch(es), Repair and paint (complete)




Tyres, No damage, Check











ALPHABET

Datos del vehículo

Marca	OPEL	Matrícula	7299-MCK
Modelo	Grandland PHEV	VIN	W0VZ4DGZ3N6829677
Versión	1.6 Turbo PHEV GS Line Auto 165kW/225CV todoterreno 165kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
26/06/2023	Aleta trasera derecha	0	MORE AUTOMOCION S.L.
08/02/2023	Sustitución	6932	NEUMATICOS ROSA, S.L.
14/07/2023	Sustitución	28029	FUTURWAGEN
04/07/2023	Rev. 30.000 kms	28083	MORE AUTOMOCION S.L.
27/08/2024	Rev. 60.000 kms	54397	ROMICAR AUTO S.L.
05/09/2024	Alineado, Sustitución	54398	ROMICAR
30/06/2025	Luna parabrisas	67832	RALARSA HOLDING S.L.
31/10/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter - COBRE, Filtro aceite - EQUIVALENTE EN EUROREPAR - Economic, Líquido lavaparabrisas - -20ºC - Nueva, Serv inspección 3º año, Tasa de gestión de aceites usados	71032	MOTOR LEYVA S.L.
09/02/2026	Contrapeso equilibrado, Embellecedor iz spoiler paragolpes tr, GESTION NFU, Neumático dl dr, Neumático dl iz, Sustituir Contrapeso equilibrado, Sustituir Embellecedor iz spoiler paragolpes tr / Desmontar y montar Spoiler paragolpes tr, Sustituir Neumático dl iz / Sustituir Neumático dl dr, Sustituir Neumático dl iz / Sustituir Válvula rueda dl iz	74318	AUTOFLOTAS AUTOMOVILES Y SERVICIOS S.L.U.
03/07/2026	Másticos, Prueba en carretera, Rejilla tr ventilación consola central, Sustituir Másticos, Sustituir Prueba en carretera, Sustituir Rejilla tr ventilación consola central, Verificar Diagnosis	79359	MOMENTUM MARKET MADRID S.R.L.
17/07/2026	Moqueta piso maletero, Sustituir Moqueta piso maletero	79389	AUTOFLOTAS AUTOMOVILES Y SERVICIOS S.L.U.

Fecha	Descripción	Kilómetros	Taller