MACADAM









Renault Captur: L780PJ

Vinnumber:	**VF1RJB00567688835**	Versionname:	**Captur 1.0 TCE 67kW Business Zen**
First Registrationdate:	**6/07/2021**	Fiscalpower:	
Expertise Mileage:	**52347**	Power Kw:	**67**
Bodytype:		Body colour	**Blanc Nacré**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**740**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Manual climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	4,2 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,0 mm	Goodyear	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	4,8 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	4,2 mm	Goodyear	Summer

Assistance equipment

Interior, Stain, Cleaning






Door FL, Dent(s), Paintless dent repair






Boot lid covering R, Crack, Replace




Bumper corner RL, Scratch(es), Repair and paint (complete)




Bumper corner RR, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VF1RJB00567688835

ALPHABET

Kenteken	L780PJ
Merk Model	Renault Captur 1.0 TCE 67kW Business Zen
Brandstofsoort	Benzine
Datum deel1	7/6/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/28/26	46,194	Onderhoudsbeurt
1/24/26	0	Accu
4/9/25	35,896	Sleutel/Kaart
4/7/25	35,864	APK
4/7/25	35,864	Bougie
4/7/25	35,864	Injector
4/7/25	35,864	Luchtfilter
4/7/25	35,864	Onderhoudsbeurt
4/7/25	35,864	Remvloeistof
4/7/25	35,864	Sleutelbatterij
4/7/25	35,864	Sleutel/Kaart
11/4/24	32,653	Onderhoudsbeurt
11/4/24	32,653	Remblokken voorzijde
7/12/23	20,743	Onderhoudsbeurt
6/27/22	9,587	Onderhoudsbeurt