



CUPRA Formentor: GR-186-GQ

Vinnumber:	VSSZZZKM5RR006868	Versionname:	1.4 e-HYBRID 204ch DSG6 Business Edition VP [5P]
First Registrationdate:	19/09/2023	Fiscalpower:	bva 6-204CH-8cv
Expertise Mileage:	159332	Power Kw:	
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Semi-leather
Type of climate control	Autom climate control		

Tyres

	245/45/18/100 V			
Winter tyres:	Fr.L.	Goodyear: 55%	Fr.R.	Goodyear: 45%
	Re.L.	Goodyear: 30%	Re.R.	Goodyear: 35%
Tyre profile depth FL				4.7
Tyre profile depth FR				5.1
Tyre profile depth RL				6.3
Tyre profile depth RR				5.9
Tyre size FL				245/45 R 18 100 V
Tyre size FR				245/45 R 18 100 V
Tyre size RL				245/45 R 18 100 V
Tyre size RR				245/45 R 18 100 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Backrest cover FL, Tear, Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Alloy rim RR, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair/replace (lump sum)




Windscreen, Stone chip(s), Windscreen repair



Rear upper boot lining, Broken, Replace



Boot lid covering R, Scratch(es), Replace



Historique Maintenance

Immatriculation: GR-186-GQ Date de 1ère immatriculation: 19/09/2023

Modèle: CUPRA FORMENTOR 1.4 e-HYBRID 204ch DSG6 Business Edition VP [5P] bva 6-204CH-8cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
09/04/2026	153.307	JEANNIN AUTOMOBILES 10	REVISION
28/01/2026	136.235	JEANNIN AUTOMOBILES 10	REVISION
21/11/2025	125.086	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
13/11/2025	124.611	JEANNIN AUTOMOBILES 10	REVISION ET CLIM ET AIR ET BOUGIES
	0		PILE DE CLE RPLT
	0		HUILE BV RPLT
28/08/2025	106.799	JEANNIN AUTOMOBILES 10	REVISION
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
07/07/2025	93.234	JEANNIN AUTOMOBILES 10	REVISION
12/04/2025	74.735	JEANNIN AUTOMOBILES 10	REVISION
19/02/2025	62.629	JEANNIN AUTOMOBILES 10	REVISION ET CLIM ET AIR ET BOUGIES
	0		PILE DE CLE RPLT
	0		HUILE BV RPLT
12/11/2024	44.890	JEANNIN AUTOMOBILES 10	REVISION
26/08/2024	29.048	JEANNIN AUTOMOBILES 10	REVISION
11/06/2024	14.627	JEANNIN AUTOMOBILES 10	REVISION