

2-DVB-849

2-DVB-849 · Titanium 1.0i Ecoboost 100pk 74kw · 2 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DVB-849	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0JXXGAHJPD28571
Model	Fiesta	Cylinder Capacity	998 ^{cm³}
Model Versions	Titanium 1.0i Ecoboost 100pk 74kw	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	03-07-2023
Color	Grey	Odometer	87.426 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	74	Number Headrests	5

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Rear Left	2 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Front Right	1 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Rear Right	2 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Wheelcover - Left Front

Damaged

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Left

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

Scratch(es)

Spray

No



Damage Part
Frontdoor - Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Other

Damage Type
Broken

Notes
Nummerplaathouder

Repair Type
Replace

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Broken	Replace & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Damaged	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Spray	No



Damage Part

Damage Type

Repair Type

Acceptable

Mirror - Rightside

Signallight broken

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Wheel - Right

Scratch(es)

Spray

No

Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Rear	Damaged	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small dent(s)	Restyle	No



Damage Part
Reardoor - Right

Damage Type
Small scratch(es)

Notes
Bekleding

Repair
Type
Plastic
Repair

Acceptable
No



Damage Part
Interior

Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable
No