

## 2-FAX-966


2-FAX-966 · 318iA Berline Business Edition · 6 August 2026 · Zaventem (BE)

### Specifications

|                      |                                |                   |                                     |
|----------------------|--------------------------------|-------------------|-------------------------------------|
| License Plate Number | 2-FAX-966                      | Fuel Type         | Gasoline                            |
| Manufacturer         | BMW                            | VIN               | WBA28FF0908E20711                   |
| Model                | 3-serie                        | Cylinder Capacity | 1.998 <sup>cm3</sup>                |
| Model Versions       | 318iA Berline Business Edition | Transmission Type | Automatisch geschakelde Transmissie |
| Body Type            | Sedan / Limousine              | First Admission   | 11-03-2024                          |
| Color                | Blue                           | Odometer          | 83.580 <sup>Km</sup>                |
| Paint Type           | Metallic                       | Numer Of Keys     | 2                                   |
| Production Year      | 2024                           | Interior          | Grey                                |
| KW                   | 115                            | Number Headrests  | 5                                   |

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Steering wheel multifunction

Steeringwheel – Heated

## Condition

Condition exterior

Adequate

Maintenance Remarks

Olie verversen over 21000 km

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

| Tire            | Profile         | Brand    | Width             | Aspect Ratio     | Radial             | Type   |
|-----------------|-----------------|----------|-------------------|------------------|--------------------|--------|
| Front Left      | 2 <sup>mm</sup> | Michelin | 225 <sup>mm</sup> | 50 <sup>mm</sup> | 17 <sup>inch</sup> | Summer |
| Rear Left       | 2 <sup>mm</sup> | Michelin | 225 <sup>mm</sup> | 50 <sup>mm</sup> | 17 <sup>inch</sup> | Summer |
| Front Right     | 2 <sup>mm</sup> | Michelin | 225 <sup>mm</sup> | 50 <sup>mm</sup> | 17 <sup>inch</sup> | Summer |
| Rear Right      | 2 <sup>mm</sup> | Michelin | 225 <sup>mm</sup> | 50 <sup>mm</sup> | 17 <sup>inch</sup> | Summer |
| Spare Tire Type | None            |          |                   |                  |                    |        |

## Damages



Damage Part

Skirt – Left



Damage Type

Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Fender – Rear Right



Damage Type

Small dent(s)

Repair Type

Restyle


Acceptable

No



Damage Part

Alloy – Right Front



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Bumper – Front



Damage Type

Scratch(es)



Repair Type

Spray

Acceptable

No



Damage Part

Alloy – Left Front



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Frontdoor – Left



Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small dent(s)

Acceptable

Yes