



IDENTIFICATION VEHICLE

Make: PEUGEOT
Model / version: 2008
Vin: VR3USHNKKNJ572075
Mileage: 75907
First registration: 28/04/2022
Color:




ADDITIONAL INFORMATION


Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✗
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
Commande radio au volant
Projecteurs à allumage automatique
Lettre repère (J)
Largeur avant 6,5
Diamètre arrière 16
Indice de vitesse avant H
Largeur arrière 215
Essence
74 kw
Métallisée vernissée

Garnitures tissu
Caméra avant
Équipement Stop & Start
Vitres de custode teintées foncées
Airbag latéraux avant
Témoin d'oubli de ceinture avant
Assistant maintien de la voie

compresseur de climatisation avec coupleur
feux de jour à LED

Radio avec système de navigation
Boîte manuelle
Projecteurs à LED
Diamètre avant 16
Largeur arrière 6,5
Hauteur avant 65
Indice de vitesse arrière H
Climatisation automatique
1199 cm3
101 ch
Freins avant à disques

Direction assistée électrique
Caméra avec vision à 180°
Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Airbag rideaux avant
Témoin d'oubli de ceinture arrière
Freinage d'urgence assistée autonome (urbain)

retroviseurs rabattables électrique

ligne d'équipement Salin

Ecran tactile
6 rapports
Matière : alliage
Diamètre arrière 16
Diamètre avant 16
Hauteur arrière 65
Largeur avant 215
Climatisation réfrigérant 1234YF
1.20 litre
Euro 6.3
Rétroviseur intérieur jour/nuit automatique
Aide au stationnement arrière
Régulateur de vitesse
Vitres portes arrière teintées foncées
Fixotoit noir
Airbag rideaux arrière
Programme électronique de stabilité ESP depuis 01.22 16520

antenne intégrée et numérique

filtre à carburant extérieur (essence)

condenseur de 20 dm² et de 12 mm d'épaisseur	batterie 70 Ah EFBC	commande hydraulique de l'embrayage
défecteur d'air double réglable pour radiateur	berceau porteur av en acier	kit réparation pneus
radiateur de 21 dm² et de 18 mm d'épaisseur	enjolveurs bas de caisse av inox	embout échappement

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Certificate of registration 1	Missing
3	Door RR	Dent(s) and scratch(es)
4	Door FR	Dent(s) and scratch(es)
5	Alloy rim FR	Dent(s) and scratch(es)

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Certificate of registration 1 - Missing



3 - Door RR - Dent(s) and scratch(es)



4 - Door FR - Dent(s) and scratch(es)



5 - Alloy rim FR - Dent(s) and scratch(es)



2 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE

Expert
22/05/2026 13:26