



Seat Arona (UKL): 2CAN964

Vinnumber:	VSSZZZKJZNR086342	Versionname:	Arona Move! 1.0TSi 95pk/cv 5p
First Registrationdate:	12/05/2022	Fiscalpower:	
Expertise Mileage:	54219	Power Kw:	70
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	over 15300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Hankook: 2 mm	Fr.R.	Hankook: 2 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm
Tyre profile depth FL	2.0			
Tyre profile depth FR	2.0			
Tyre profile depth RL	3.0			
Tyre profile depth RR	3.0			
Tyre size FL	205/60 R 16 92 H			
Tyre size FR	205/60 R 16 92 H			
Tyre size RL	205/60 R 16 92 H			
Tyre size RR	205/60 R 16 92 H			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	260			
Tyre make FR	260			
Tyre make RL	260			
Tyre make RR	260			

Assistance equipment

Spare wheel	Yes	Compressor	Yes
Repair kit	Yes	Jack	Yes

Ignition key, Not functioning (well), Acceptable



Backrest cover RL, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Outer door handle FL, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Repaired, Acceptable



Side window trim RR, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Replace



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Kenteken	2CAN964
Merk Model	Seat Arona Move 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	5/18/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/23/25	41,633	klein materiaal	
10/23/25	41,633	luchtfILTER interieur	Vervangen
10/23/25	41,633	remvloeistof	Vervangen
10/23/25	41,633	ruitenwisserrubber achter	Vervangen
10/23/25	41,633	ruitenwisserrubber vooraan	Vervangen
10/23/25	41,633	ruitenwisservloeistof	Bijvullen/-laden
10/23/25	41,633	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren
3/13/25	32,285	klein materiaal	
3/13/25	32,285	koelwatervloeistof	Bijvullen/-laden
3/13/25	32,285	Onderhoudsbeurt (variabel interval)	Uitvoeren
3/13/25	32,285	ruitenwisservloeistof	Bijvullen/-laden
2/8/24	25,498	klein materiaal	N.v.t.
2/8/24	25,498	koelwatervloeistof	Bijvullen/-laden
2/8/24	25,498	ruitenwisservloeistof	Bijvullen/-laden
2/8/24	25,498	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren