



PEUGEOT 308 3

-	
VIN	VR3FPHNSTPY629158
Première immatriculation	24/10/2023

DÉTAILS DE L'INSPECTION

INFORMATIONS SUR LE VÉHICULE

VIN	VR3FPHNSTPY629158	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	24/10/2023	Couleur intérieur	Noir
Type de carburant	Essence	Couleur carrosserie	Noir
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Certificat immatriculation (original)	Original
Nbre clés total	2	Certificat immatriculation (original)	Oui
Nbre clés télécommandes	2	Entretien	Oui
Manuel d'utilisation	Oui		

OPTIONS

Nature de peinture	Metallisé
--------------------	-----------

DAMAGES

Interior



1 | Interior

Damage type	Stain
Repair mode	Cleaning

Exterior



2 | Alloy rim RR

Damage type	Scratch(es)
Repair mode	Acceptable



3 | Alloy rim FR

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



4 | Wing FL

Damage type	Scratch(es)
Repair mode	Paint



5 | Door FL

Damage type	Scratch(es)
Repair mode	Paint



6 | Door RL

Damage type	Scratch(es)
Repair mode	Acceptable



7 | Wing RL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



8 | Bumper F

Damage type	Deformed / Strained
Repair mode	Repair and paint (complete)



9 | Bumper moulding FR

Damage type	Scratch(es)
Repair mode	Replace



10 | Daytime running light FR

Damage type	Scratch(es)
Repair mode	Replace



11 | Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



12 | Outer sill R

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



13 | Bumper R

Damage type	Deformed / Strained
Repair mode	Repair and paint (complete)



14 | Bumper spoiler Rear

Damage type	Broken
Repair mode	Replace



15 | Boot moulding

Damage type	Deformed / Strained
Repair mode	Replace and paint



16 | Tailgate / Boot

Damage type	Scratch(es)
Repair mode	Paint

Commercial photos

