



IDENTIFICATION VEHICLE

Driver name:
Make: VOLVO
Model / version: XC40
Vin: YV1XZEFVKN2762656
Plate:
Mileage: 74178
First registration: 14/03/2022
Color: DENIM BLUE M


ADDITIONAL INFORMATION





Category:
Transmission:
Interior color: ?
Metallic paint: ?
Type of lining: ?
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
Projecteurs à LED
Diamètre avant 19
Largeur arrière 8,5
Freins avant à disques
Rétroviseur gauche jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique
Volant chauffant
Alarme
Airbag de genoux
Keyless Entry
airbag passager désactivable
ceintures de sécurité de type B
poignées de portes éclairées

12 haut-parleurs
Matière : alliage
Diamètre arrière 19
Climatisation automatique 2 zones
Rétroviseur gauche à réglage mémorisé
Rétroviseur droit jour/nuit automatique
Siège avant gauche chauffant

Caméra arrière de recul
détecteur de pluie essuie-vitre
depuis n°châssis 746 261
sièges baquet av
aide au parking av/ar Génération 3
pack éclairage intérieur
sigle chauffant

Projecteurs directionnels
Lettre repère (J)
Largeur arrière 7,5
Métallisée vernissée
Rétroviseur droit à réglage mémorisé
Rétroviseurs carbone
Sièges avant chauffants

Ouverture du coffre électriquement
Fixotoit
rétroviseurs électrique "8D06"
grille de calandre active Shutter-System
sécurité enfants électrique
grille de calandre "BEV"
1 vitesse

235/50 R 19 .. H

galerie de pavillon noir
Radar Argus
Thaïlande

avant 235/50 R 19 .. V arrière 255/45 R 19
.. V
connexion chargeur rapide Type 2
batterie haute tension 69 kWh
système "Electric"

câble de charge pour prise domestique
Mode 3 Type 2 16A
CAB CHARG SCHUKO 10A
moteur électrique av 170 kW (Total)

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	1	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons		?
Front right	5 mm			All-seasons		?
Rear left	5 mm			All-seasons		?
Rear right	5 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Alloy rim FL polished	Dent(s) and scratch(es)

Total: 1

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

2 - Alloy rim FL polished - Dent(s) and scratch(es)



1 - Bodywork - Dent(s) and scratch(es) - Renta®

