


## Vehicle details

|                   |                    |              |                        |                           |               |
|-------------------|--------------------|--------------|------------------------|---------------------------|---------------|
| VIN               | WBY7X4104 0SZ93053 | Brand        | BMW                    | Maintenance date          | -             |
| Licence Plate     |                    | Model        | ix3 80kWh Executive 5d | Maintenance mileage       | -             |
| Registration date | 07/07/2021         | Year         | 2021                   | Exterior Color            | Blue Metallic |
| Odometer          | 148 633 km         | Engine size  | -                      | Interior Color            | Black         |
| Fuel              | Electric           | Body Type    | -                      | Next technical inspection | -             |
| Seats             | -                  | Transmission | Automatic              | CO2                       | -             |
| Doors             | 5                  | Gears        | -                      |                           |               |

## Inspection Details

|                 |            |                 |  |
|-----------------|------------|-----------------|--|
| Inspection date | 08/06/2026 | Inspection loc. |  |
|-----------------|------------|-----------------|--|



### Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| Leather                    | ✓ |
| GPS system                 | ✓ |
| Sliding roof               | ✓ |
| Panoramic roof             | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Heating seats              | ✓ |
| Electric seats             | ✓ |
| Tow                        | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

### Removable element

|                  |   |
|------------------|---|
| Load cover       | ✓ |
| Vehicle charger  | ✓ |
| Wireless charger | ✗ |


### Technical Document

|             |   |
|-------------|---|
| User manual | ✓ |
| Spare key   | ✓ |
| Remote key  | ✓ |

## Tyres

### Winter kit

Goodyear 245/45/20 Winter 8.0 mm



Goodyear 245/45/20 Winter 8.0 mm



Goodyear 275/40/20 Winter 6.0 mm



Goodyear 275/40/20 Winter 6.0 mm


## Exterior

2



|             |            |
|-------------|------------|
| Part        | Wing       |
| Position    | Front left |
| Damages     | Scratched  |
| Severity    | -          |
| Repair mode | Repair     |

3




|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 20" |
| Position    | Back left       |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |

4



|             |               |
|-------------|---------------|
| Part        | Wing moulding |
| Position    | Back right    |
| Damages     | Scratched     |
| Severity    | -             |
| Repair mode | Replace       |

5



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back right         |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

6




|             |               |
|-------------|---------------|
| Part        | Door moulding |
| Position    | Back right    |
| Damages     | Scratched     |
| Severity    | -             |
| Repair mode | Replace       |

7



|             |               |
|-------------|---------------|
| Part        | Door moulding |
| Position    | Front right   |
| Damages     | Scratched     |
| Severity    | -             |
| Repair mode | Replace       |

|    |                                                                                    |             |                    |
|----|------------------------------------------------------------------------------------|-------------|--------------------|
| 8  |   | Part        | Door               |
|    |                                                                                    | Position    | Front right        |
| 10 |   | Damages     | Dent & Chips       |
|    |                                                                                    | Severity    | Diameter (mm) > 20 |
|    |                                                                                    | Repair mode | Repair             |
|    |                                                                                    |             |                    |
| 9  |  | Part        | Bonnet             |
|    |                                                                                    | Position    | -                  |
|    |                                                                                    | Damages     | Scratched          |
|    |                                                                                    | Severity    | -                  |
|    |                                                                                    | Repair mode | Repair             |
|    |                                                                                    |             |                    |
|    |                                                                                    | Part        | Windscreen         |
|    |                                                                                    | Position    | -                  |
|    |                                                                                    | Damages     | Scratched          |
|    |                                                                                    | Severity    | -                  |
|    |                                                                                    | Repair mode | For info           |
|    |                                                                                    |             |                    |

Others

|   |                                                                                   |             |                  |
|---|-----------------------------------------------------------------------------------|-------------|------------------|
| 1 |  | Part        | Wireless charger |
|   |                                                                                   | Position    | -                |
|   |                                                                                   | Damages     | Missing          |
|   |                                                                                   | Severity    | -                |
|   |                                                                                   | Repair mode | For info         |
|   |                                                                                   |             |                  |