# VEHICLE REPORT

IT · 06/11/2026
2026-11-06 09:30

VIN: Targa: Merchant:

## VEHICLE DETAILS

| | | | |
|---|---|---|---|
| Targa | | First Registration | **2007-12-21** |
| Marca | N/A | Mileage | N/A |
| Modello e Allestimento | | Keys | N/A |
| VIN | | Owners | **4** |
| Merchant | | Seats | **5** |
| Branch | | Previous Use | **AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE** |
| KW | **160** | VAT | N/A |
| CC | **26** | Country | **IT** |
| Fuel | **GASOL** | Euro | **EURO4** |
| GPL | **Non presente** | Cambio | **AUTOMATICO** |
| Gancio | **14/09/2012** | | |

## CAR PHOTOS (56)


*Engine compartment*


*Engine compartment*



*Engine compartment*


*Engine compartment*


*Engine compartment*


*Engine compartment*


*Front right*


*Front left*


*Underbody view*


*Left side front*


*Left side front*


*Rear fender left*


*Left side front*


*Front.*



*Engine compartment*


*Rear fender left*


*Front*


*Left side front*


*Rear*


*Rear*


*Rear*


*Front left*


*Front left*


*Underbody.*



*Rear fender left.*


*Right side rear*


*Left side front*


*Left side front*


*Rear fender left*


*Left side front*


*Rear fender left*


*Left side rear*


*Left side rear*


*Interior front*


*Interior front*


*Front door left*



Interior rear



Interior front



Front door left



Trunk



Interior rear.



Front door left



Interior front



Front door left



Interior front



Center console and dashboard



Center console and dashboard



Speedometer with started engine.



Speedometer with started engine



Interior front



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Trunk



Additional photos (optional)



Interior rear