

**BMW 3 Touring:**

Vinnumber:	WBA71DZ010FN17632	Versionname:	BMW 3 TOURING (G21) 318iA (115 kW) 156PK
First Registrationdate:	1/07/2022	Fiscalpower:	5d/p AUT (7ADZ)
Expertise Mileage:	85914	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2331
Fueltype:	Petrol		
Maintenance:	OK		
Maintenance:	dans 6000km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection**Tyres**

225/50/17/98 Y				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 17 98 Y
Tyre size FR				225/50 R 17 98 Y
Tyre size RL				225/50 R 17 98 Y
Tyre size RR				225/50 R 17 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2278,23
Ignition key, Missing, Replace	350,09



Seat cover FL, Stain, Cleaning	29,16
--------------------------------	-------



Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Seat cover R, Stain, Cleaning	29,16
-------------------------------	-------



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------



Door FL, Dent(s) and scratch(es), Repair and paint (complete)	505,30
---	--------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------




Wing RR, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing RR, Scratch(es), Polish	0,00
------------------------------	------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	505,30
---	--------



Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00
---	------



Bodywork, Not original part, Remove lettering	0,00
---	------

