MACADAM










VOLKSWAGEN CADDY CARGO: GH-416-QN

Vinnumber:	**WV1ZZZSKZNX055292**	Versionname:	**VOLKSWAGEN CADDY CARGO 2.0 TDI 122ch 4motion Business VU [4P] bvm 6-122CH-7cv (fourgonnettesimple cabine)**
First Registrationdate:	**21/07/2022**	Fiscalpower:	
Expertise Mileage:	**86805**	Power Kw:	**90**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/60/16/96 H**			
	Fr.L.	**Continental: 40%**	Fr.R.	**Continental: 45%**
	Re.L.	**Continental: 35%**	Re.R.	**Continental: 35%**

Tyre profile depth FL	**5.7**
Tyre profile depth FR	**5.4**
Tyre profile depth RL	**5.8**
Tyre profile depth RR	**5.9**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Bumper F, Scratch(es), Acceptable




Sliding door R, Dent(s), Acceptable





Outside rear-view mirror housing R, Scratch(es), Replace




Outside rear-view mirror housing R, Scratch(es), Replace




Boot door panel RR, Dent(s), Acceptable





Bodywork, Not original part, Sticker removal small




ALPHABET

Historique Maintenance

Immatriculation: **GH-416-QN** Date de 1ère immatriculation: **21/07/2022**

Modèle: **Volkswagen CADDY CARGO 2.0 TDI 122ch 4motion Business VU [4P] bvm 6-122CH-7cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
18/08/2026	86.459	AUTOPOLE MAUREL CASTRES	BATTERIE RPLT
18/08/2026	86.459	AUTOPOLE MAUREL CASTRES	BATTERIE RPLT
18/08/2026	86.459	AUTOPOLE MAUREL CASTRES	BATTERIE RPLT
04/05/2026	80.807	CONTITRADE FRANCE LA CROIX ST OUEN	REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
16/01/2026	74.262	SOC EXPLOIT GARAGE GUIRAUD & FILS	BALAIS ESSUIE GLACE AV
			PLAQUETTES AR RPLT
			REVISION
12/11/2025	69.989	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
07/07/2025	60.532	CONTITRADE FRANCE	REPARATION DE ROUE
			PERMUTATIONS PNEUS
14/11/2024	46.485	CONTITRADE FRANCE	PERMUTATIONS PNEUS
			REPARATION DE ROUE
04/11/2024	45.949	SOC EXPLOIT GARAGE GUIRAUD & FILS	REVISION ET CLIM
			ADBLUE
			BALAIS ESSUIE GLACE AV
			DIVERS
			LIQUIDE DE FREIN
12/06/2024	37.603	CONTITRADE FRANCE	PERMUTATIONS PNEUS
			REPARATION DE ROUE
14/11/2023	27.135	CONTITRADE FRANCE	REPARATION DE ROUE
13/12/2022	7.468	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS 4 SAISONS
19/08/2026		AUTOPOLE MAUREL	Credit note - Wear and tear maintenance