



PEUGEOT Expert: 1222-MLV

Vinnumber:	VF3VBYHVMP7862451	Versionname:	Furgón BlueHDi 120 S&S 6v Standard furgón 88kW 4P manual
First Registrationdate:	28/11/2023	Fiscalpower:	
Expertise Mileage:	152024	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Rear parking sensors:	
Windows electric F:			
Cruise Control:			
Type of climate control:	Manual climate control		

Tyres

215/65/16/104 T				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 16 104 T
Tyre size FR				215/65 R 16 104 T
Tyre size RL				215/65 R 16 104 T
Tyre size RR				215/65 R 16 104 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Dashboard, Scratch(es), Repair/replace (lump sum)



Door panel RL, Scratch(es), Repair/replace (lump sum)



Door panel RR, Scratch(es), Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Wing FL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Rear light L, Broken, Replace



Bumper moulding F, Scratch(es), Repair and paint (complete)



Sliding door R, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Paint



Wheel bolt cover FR, Missing, Replace



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Scratch(es), Paint



Boot door panel RR, Scratch(es), Paint



Tyres, No damage, Check

