



HYUNDAI I30 FASTBACK: FY-397-LM

Vinnumber:	TMAH3H1DGMJ025240	Versionname:	HYUNDAI I30 FASTBACK 1.5 T-GDI 160 MHEV DCT-7 FASTBACK N LINE VP [5P] bva 7-160CH-8cv (bi-corps)
First Registrationdate:	8/04/2021	Fiscalpower:	118
Expertise Mileage:	171315	Power Kw:	118
Bodytype:	Berline	Body colour:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Semi-leather
			Lining Alcantara

Tyres

	225/40/18/92 Y			
Summer tyres:	Fr.L.	Hankook: 75%	Fr.R.	Hankook: 80%
	Re.L.	Michelin: 45%	Re.R.	Michelin: 45%
Tyre profile depth FL				3.4
Tyre profile depth FR				3.0
Tyre profile depth RL				5.1
Tyre profile depth RR				5.2
Tyre size FL				225/40 R 18 92 Y
Tyre size FR				225/40 R 18 92 Y
Tyre size RL				225/40 R 18 92 Y
Tyre size RR				225/40 R 18 92 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Side repeater L, Broken, Replace



Outside rear-view mirror base L, Broken, Replace



Door RL, Scratch(es), Polish



Bumper moulding FR, Scratch(es), Replace



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **FY-397-LM** Date de 1ère immatriculation: **08/04/2021**

Modèle: **Hyundai I30 FASTBACK 1.5 T-GDI 160 MHEV DCT-7 FASTBACK N LINE VP [5P] bva 7-160CH-8cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
20/04/2026	167.725	AUTOMOBILES DELAHAYE	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		BOUGIES ALLUMAGE CTRL
	0		LIQUIDE DE FREIN
05/11/2025	152.550	AUTOMOBILES DELAHAYE	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
28/04/2025	135.418	AUTOMOBILES DELAHAYE	DISQUES PLAQUETTES AV RPLT
11/04/2025	134.643	AUTOMOBILES DELAHAYE	PILE DE CLE RPLT
	0		REVISION
23/10/2024	120.753	AUTOMOBILES DELAHAYE	LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV AR
06/05/2024	104.030	AUTOMOBILES DELAHAYE	REVISION
10/10/2023	89.380	AUTOMOBILES DELAHAYE	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		BOITIER D ALLUMAGE RPLT
08/03/2023	69.524	AUTOMOBILES DELAHAYE	DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
09/02/2023	67.542	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
13/10/2022	55.976	AUTOMOBILES DELAHAYE	REVISION
28/04/2022	37.977	AUTOMOBILES DELAHAYE	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
22/02/2022	32.988	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
29/11/2021	23.432	PROFIL PLUS	REPLACEMENT PNEUS ETE
24/11/2021	22.763	AUTO NORD	REVISION