


2-FPG-230 · Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06 · 22 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FPG-230	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJXRR180019
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	01-07-2024
Body Type	5 door hatchback	Odometer	73.299 ^{km}
Color	Blue	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	85		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications


Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	1 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Windscreen – Front



Damage Type

Chipped

Repair Type

Window Repair

Acceptable

No



Damage Part

Fender – Rear Left



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Frontdoor – Left



Damage Type

Door-edge chipped



Repair Type

Acceptable

Acceptable

Yes



Damage Part

Hood

Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Overfender

Damage Type

Scratch(es)

Repair Type

Replace

Acceptable

No



Damage Part

Reardoor - Right

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part
Bumper – Rear



Damage Type
Scratch(es)



Repair Type
Spray

Acceptable
No



Damage Part
Interior



Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable
No