

» Overview

Order number: 1002389032
Order completed: 10.04.2026 11:39
Report number: 10399213
VIN: WVVZZZCD7RW185786



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	EstateCar
Make:	Volkswagen
Model:	Golf
Manufacturers and type code:	0603 / CNZ
Date of first registration:	02.04.2024
Mileage:	21,887 km
Proof of mileage:	ReadOff
Exterior colour:	Uranograu
Roof colour:	Uranograu
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,498 ccm
Performance:	110 kW (150 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	5
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining Alcantara
Interior colour:	Soul-Schwarz/Soul-Schwarz/Schwarz/ Storm Grey
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	04.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	0 Day(s)

12-V outlet in luggage compartment	Driver alert system
2 LED reading lights in front and 2 in rear	Driver and front passenger airbag with front passenger airbag deactivation
2 USB-C ports in the front, 2 USB-C charging sockets on the center console in rear, charging capacity up to 45 W	Driving on the right
3 head restraints in rear	Dual-clutch transmission DSG DQ200
30-color ambient lighting	Dynamic headlight range control
3-point seat belts for the outer rear seats	Electromechanical parking brake with Auto Hold function
3-point seat belts in front with height adjustment and seat belt pretensioners	Electromechanical speed-sensitive power steering
4 alloy wheels "Nottingham" 7.5J x 17	Electronic differential lock XDS
4+1 speakers	Electronic engine sound
4-cylinder SI engine 1.5 l	Electronic immobilizer
4-cylinder SI engine 1.5 l eTSI, 110 kW	Electronic restriction of top speed
7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF	Electronic Stability Control and electromechanical brake booster
Activated carbon canister (Evaporative Emission Control System (EVAP))	Elimination of nameplate for engine designation on luggage compartment lid
Adaptive Cruise Control ACC stop & go incl. speed limiter	Emergency call service, 10-year contract duration as of initial delivery, condition: mob. phone network available
Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear	Emission standard EU6 AP
App-Connect for Apple CarPlay and Android Auto	Equipment options subset for Germany
Auto. Emergency Braking Front Assist with Pedestrian and Cyclist Monitoring	ergoActive driver seat with power adjustment, memory feature and adjustable thigh support
Auto-dimming interior rearview mirror	Ext. mirrors, power-adjustable and heated, with memory feature and front passenger ext. mirror lowering function
Automatic headlight control with LED separate daytime running light and entry and exit lighting	Extended pedestrian protection
Automatically-heated washer nozzles in front	Exterior mirrors: aspherical on driver side, convex on front passenger side
Basic equipment variant	First aid kit, warning triangle and safety vest
Battery 380 A (59 Ah) EFB+	Four-link suspension
Belt-driven integrated starter alternator 48 V 110 - 250 A	Front center armrest, height- and longitudinally adjustable
Body-colored bumpers, air intake with chrome fin	Front stabilizer bar
Body-colored exterior mirror housings and door handles	Front-wheel drive
Car2X	Fuel system for fuel-injected SI engine
Carpet mats in front and rear	Gearshift knob/handle in plastic
Chrome elements on power mirror and window regulator switches, chrome trims on the vents	Green heat-insulating glass windows on sides and in rear
Chrome trim on the side window bottoms	Hatchback
Cornering light and poor weather light	Headliner
Curtain airbags in front and rear, side airbags in front, center airbag	Heated front seats
Decorative inserts "New Brushed Dark Metal" for dashboard and door trim panels in front	High-beam control Light Assist
Delivery "Autostadt Wolfsburg"	Hybrid drive system mHEV
Digital radio reception DAB+	Illuminated molding between headlamps and illuminated door handle recesses
Disc brakes in front	Illuminated vanity mirrors in sun visors
Disc brakes in rear	Initial standard fuel filling
Diversity antenna for FM reception	Inserts of front seats and outer rear seats in ArtVelours microfleece
Door and side trim panel	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer

ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat, compatible for i-Size	Special identification label for EC for M1 passenger vehicles
Keyless Start without SAFELOCK	Sports comfort seats in front
Laminated safety glass windshield, heat- and sound-insulating	Sports equipment
Leather multi-function steering wheel, heated, with shift paddles	Standard battery/alternator capacity
LED light unit in front footwell, selectable light color	Standard climatic zones
LED Plus headlamps	Standard curb weight range
LED rear combination lamps	Standard engine starter
Left-hand drive	Standard manufacturing sequence
Lights & Vision package incl. high-beam control Light Assist	Standard paint coating
LongLife Service Regime	Standard pedal cluster
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Standard rear seat release
Manual in German (Germany)	Standard roof
Mobile phone interface with inductive charging feature	Standard wheel bolts
Multi-color Digital Cockpit Pro, selection of different info profiles possible	Start-stop system with regenerative braking
Multifunction camera	Surround lighting with welcome light
No special edition	Suspension range 05 installation control only, no requirement forecast
No special purpose vehicle, standard equipment	Tailgate/trunk lid unlocking from outside
Non-folding front passenger seat backrest	Tire Mobility Set: 12-volt compressor and tire sealant
Non-smoker's package: Storage compartment and 12 V outlet in front	Tire Pressure Monitoring System
Not hot country	Tires 225/45 R17
Oncoming vehicle braking when turning and swerve support	Tool kit
Online service, with OCU, without head unit coding, without engine immobilizer interconnection	Transport protection film (minimum protection) with additional transport protection measures
Operating permit, alteration	Two-tone horn
Operating voltage 12 V	Type approval country Germany
Park Distance Control - warning signals for obstacles in the front and rear	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest
Part set without country-specific prescriptive standard	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
Preparation for We Connect and We Connect Plus or VW Connect and VW Connect Plus	Vehicle class differentiation -5H0-
Radio "Composition"	Vehicles without special upgrade measures
Rain sensor	Warning signal and warning light for front and rear seat belts not fastened
Rear exhaust tailpipe (standard)	Weight range 3 installation control only, no requirement forecast
Rear floor panel module, type 1	Wheelbase
Rear fog light on one side, back-up light on both sides	Winter package
Rear shock absorption, basic version 1	Without Adaptive Chassis Control
Rear stabilizer bar	Without additional front underbody guard
Refrigerant R1234yf	Without additional tires
Regional code " ECE " for radio	Without alcohol interlock
Safety-optimized front head restraints	Without auxiliary heater/parking heater
Semi-automated driving assistance Travel Assist and lane keeping system Lane Assist	Without camera systems/accident sensors
Service indicator 30 000 km or 2 years (variable)	Without charging cable
Shock absorption in front	Without decals and emblems
	Without dynamic road sign display

- Without electric motor (hybrid)
- Without extended safety system
- Without fire extinguisher
- Without headlamp washer system, with washer fluid level indicator
- Without head-up display
- Without heat accumulator/auxiliary heater
- Without hill start assist/hill descent control/comfort driving assist
- Without lane change assist
- Without locking and starting systems
- Without mode 3 charging cable
- Without navigation device
- Without partition
- Without preparation for rotating beacon/siren combination
- Without preparation for two-way radio installation
- Without roof rails
- Without seat ventilation/massage seat
- Without second battery
- Without special body measures
- Without speed limiter
- Without trailer hitch
- Without UN-ECE cybersecurity & software update
- Without voice control

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Nexen	Front	Left	Summer	Aluminium	225/45 R 17 91 W	7.0 mm
Nexen	Front	Right	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Other	Rear	Left	Summer	Aluminium	225/45 R 17 91 Y	9.0 mm
Other	Rear	Right	Summer	Aluminium	225/45 R 17 91 Y	9.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 01.2028

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Service	Maintenance	Execute
2	Roof	Dent(s)	Paintless dent repair

» Usage Damages

Nr	Location	Damage type	Repair type
1	Windscreen	Stone chip(s)	Acceptable

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZCD7RW185786

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

Yes

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures




Front Left 3/4



Front Right 3/4




Rear Left 3/4




Rear Right 3/4




Mileage



Tools



Sill outer L



Sill outer R




Chassis nr




Wheel FL



Wheel FR




Wheel RL




Wheel RR




Central console




Engine compartment



Documents



Interior arrangement




Registration Certificate




History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Service - Maintenance - Execute

2 - Roof - Dent(s) - Paintless dent repair



USAGE DAMAGES

1 - Windscreen - Stone chip(s) - Acceptable

