



CITROËN Berlingo: 4156-LRB

Vinnumber:	VR7EFYHYCMN528336	Versionname:	Citroen Talla M BlueHDi 100 CONTROL furgón derivado de turismo 75kW 3P manual
First Registrationdate:	11/06/2021	Fiscalpower:	
Expertise Mileage:	188192	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Tow bar
Number keys remote	1	Radio
Windows electric F		Roof rack
Cruise Control		
Type of climate control	Manual climate control	

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Steering wheel, Worn, Replace			



Wing RL, Scratch(es), Paint




Door FL, Scratch(es), Paint



Windscreen, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Boot door panel RR, Scratch(es), Paint



Boot door panel RL, Scratch(es), Paint



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

