DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	ZAC5JACL3 RJL26140	Registration date	28/03/2025	Exterior Color	Unknown
Brand	JEEP	Licence Plate	EU-FB 1684	Odometer	42 475 km
Model	AVENGER 1.2 GSE T3 GDI Altitude				

Inspection Details

Arrival Date	18/08/2026	Inspection ID	7123931	Inspection date	24/08/2026
Assign Date	18/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Schöneck



Generic equipment

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 215/60/17 V All seasons 5.0 mm		Goodyear 215/60/17 V All seasons 5.0 mm	
Goodyear 215/60/17 V All seasons 6.0 mm		Goodyear 215/60/17 V All seasons 6.0 mm	





Exception / Damage

1



Part	Door	Repair Time	-	Part Cost	-
Position	Back left	Repair Cost	-	Gross Cost	150.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	150.00€	**Net Cost**	**150.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	100.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	100.00€	**Net Cost**	**100.00€**

Summary Inspection

Gross Price	250.00€	Depreciation	-	Net Price	250.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	250.00€	-	-	250.00€