



**Renault Kangoo:**

Vinnumber:	<b>VF1FWD0S163248375</b>	Versionname:	<b>Kangoo 1.5 dCi Energy 55kW Comfort</b>
First Registrationdate:	<b>27/06/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>164883</b>	Power Kw:	<b>55</b>
Bodytype:		Body colour:	<b>Blanc Minéral standardlak</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Type of rims (mounted):	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Parking lot:	<b>939</b>
Number of seats:	<b>2</b>		
Type of rims (mounted):	<b>Steel</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
GPS		Sliding door right-side
Manual climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 91 / T / Steel	4,1 mm	Vredestein	All season
	Right	195 / 65 / 15 / 91 / T / Steel	4,0 mm	Vredestein	All season
Rear	Left	195 / 65 / 15 / 91 / T / Steel	7,2 mm	Goodyear	All season
	Right	195 / 65 / 15 / 91 / T / Steel	4,2 mm	Goodyear	All season

**Assistance equipment**

Number of charging cables (rapid charge)	<b>0</b>
--	----------

Interior, Dirty, Cleaning



Door panel RR, Broken, Replace



Door FL, Dent(s), Repair and paint (complete)




Windscreen, Stone chip(s), Windscreen repair



Boot door panel RR, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair

