


Tesla 3: [redacted]

Vinnumber:	LRW3E7FA1MC246600	Versionname:	Model 3 50kWh RWD Standard Range Plus automaat
First Registrationdate:	18/06/2021	Fiscalpower:	
Expertise Mileage:	188813	Power Kw:	225
Bodytype:		Body colour	Solid Black
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	666
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	1	Lining leather
GPS		Panoramic roof
Autom climate control		Rear parking sensors
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 15 / 18 / 98 / V / Aluminium	4,7 mm	Bridgestone	Winter
	Right	235 / 15 / 18 / 98 / V / Aluminium	5,1 mm	Bridgestone	Winter
Rear	Left	235 / 15 / 18 / 98 / V / Aluminium	4,9 mm	Bridgestone	Winter
	Right	235 / 15 / 18 / 98 / V / Aluminium	7,7 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (rapid charge)	1
--	---

Ignition key, Missing, Replace

No pictures to display

Door RL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Wing RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)




Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot carpet, Chemical pollution, Chemical cleaning



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Deformed / Strained, Replace and paint

