



Renault Clio: [redacted]

Vinnumber:	VF1RJA00167096018	Versionname:	
First Registrationdate:	5/10/2021	Fiscalpower:	
Expertise Mileage:	118603	Power Kw:	67
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1405
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

195/55/16/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 92 H
Tyre size FR				195/55 R 16 92 H
Tyre size RL				195/55 R 16 92 H
Tyre size RR				195/55 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1329,51
Seat cover R, Stain, Cleaning	29,16



Seat cover FL, Damaged, Acceptable 0,00



Bumper F, Bad repair, Check 0,00



Windscreen, Repaired, Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Bumper R, Scratch(es), Repair and paint (complete) 237,26



Rear window, Scratch(es), Replace 257,63



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RR, Scratch(es), Acceptable 0,00



Roof, Chemical pollution, Repair and paint (complete) 539,40

