



Mercedes-Benz CLA 180: L327DD

Vinnumber:	W1K1183101N221396	Versionname:	CLA180d 1.5 85kW Business Solution Luxury DCT
First Registrationdate:	7/05/2021	Fiscalpower:	
Expertise Mileage:	100835	Power Kw:	85
Bodytype:		Body colour	Nachtzwart
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Diesel	Parking lot	781
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining leather
GPS		Sun Roof electric
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 95 / V / Aluminium	4,2 mm	Michelin	Winter
	Right	205 / 55 / 17 / 95 / V / Aluminium	3,5 mm	Michelin	Winter
Rear	Left	205 / 55 / 17 / 95 / V / Aluminium	4,2 mm	Michelin	Winter
	Right	205 / 55 / 17 / 95 / V / Aluminium	6,0 mm	Michelin	Winter

Assistance equipment

Service, Maintenance, Execute



Interior, Dirty, Cleaning



Wing RL, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Kenteken	L327DD
Merk Model	Mercedes-Benz CLA180d 1.5 85kW Business Solution Luxury DCT
Brandstofsoort	Diesel
Datum deel1	07-05-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
04-05-26	91.363	APK
24-06-25	72.157	Onderhoudsbeurt
24-06-25	72.157	Remvloeistof
24-06-25	72.157	Ruitenwischerblad(en) voorzijde
24-04-25	70.835	APK
18-06-24	57.051	Brandstoffilter
18-06-24	57.051	Luchtfilter
18-06-24	57.051	Onderhoudsbeurt
18-06-24	57.051	Ruitenwischerblad(en) voorzijde
03-06-24	56.472	Vervanging band
03-05-24	55.454	APK
28-12-23	49.597	Reparatie band(en)
30-05-23	39.768	Onderhoudsbeurt
30-05-23	39.768	Remvloeistof
02-05-22	16.024	Onderhoudsbeurt