



**Volkswagen Transporter:**

Vinnnumber:	<b>WV1ZZZ7HZMH037615</b>	Versionname:	<b>Transporter 6.1 2.0 TDI 110kW L1H1 GB 7-DSG</b>
First Registrationdate:	<b>4/01/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>179187</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Reflex Zilver Metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Parking lot:	<b>960</b>
Number of seats:	<b>2</b>		
Type of rims (mounted):	<b>Steel</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
Manual climate control		Hook
Radio multimedia		Sliding door right-side

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 65 / 16 / 109 / T / Steel	7,5 mm	Bridgestone	Winter
	Right	215 / 65 / 16 / 109 / T / Steel	7,3 mm	Bridgestone	Winter
Rear	Left	215 / 65 / 16 / 109 / T / Steel	8,8 mm	Vredestein	Winter
	Right	215 / 65 / 16 / 109 / T / Steel	8,7 mm	Vredestein	Winter

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

**Interior, Dirty, Cleaning**



**Door FL, Bad repair, Repair and paint (complete)**



**Side wall RL, Bad repair, Repair and paint (complete)**



**Bonnet, Dent(s) and scratch(es), Repair and paint (complete)**



Bumper F, Scratch(es), Smart repair



Sliding door R, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Boot door lining L, Scratch(es), Replace



Bumper R, Scratch(es), Smart repair



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Bodywork, Chemical polution, Polish

