MACADAM











BMW X2 (UKL): 2AWA571

Vinnumber:	**WBAYN910805T90174**	Versionname:	**X2 (F39) 25e xDrive 1.5i 220pk/cv 5p Aut.**
First Registrationdate:	**11/08/2021**	Fiscalpower:	
Expertise Mileage:	**134356**	Power Kw:	**92**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**NOT OK**		
Maintenance	**OH sinds 06/2026**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/17/97 Y**			
	Fr.L.	**Dunlop: 6 mm**	Fr.R.	**Dunlop: 5 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/55 R 17 97 Y**
Tyre size FR	**225/55 R 17 97 Y**
Tyre size RL	**225/55 R 17 97 W**
Tyre size RR	**225/55 R 17 97 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**

MOT certificate, Missing, Replace



Service, Maintenance, Check



Seat cover FR, Stain, Cleaning




Windscreen, Stone chip(s), Windscreen repair





Wing FL, Dent(s) and scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Acceptable




Bodywork, Not original part, Remove lettering




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBAYN910805T90174

ALPHABET

Kenteken	2AWA571
Merk Model	BMW X2 (F39) 25e xDrive 1.5i 220pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	8/11/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/27/26	128,384	BMW/MINI service standaard omvang	Uitvoeren
5/27/26	128,384	controle niveaus	Uitvoeren
5/27/26	128,384	klein materiaal	
5/27/26	128,384	remblokken achter	Vervangen
5/27/26	128,384	remvloeistof	Vervangen
1/28/26	108,214	BMW/MINI service standaard omvang	Uitvoeren
1/28/26	108,214	diagnose	Uitvoeren
1/28/26	108,214	klein materiaal	
1/28/26	108,214	ruitenwisservloeistof	Vervangen
1/28/26	108,214	service microfilter	Uitvoeren
1/28/26	108,214	service motorolie	Uitvoeren
12/18/24	71,420	batterij	Vervangen
12/18/24	71,420	BMW/MINI service standaard omvang	Uitvoeren
12/18/24	71,420	BMW/MINI service voertuig-check	Uitvoeren
12/18/24	71,420	bougie	Vervangen
12/18/24	71,420	klein materiaal	N.v.t.
12/18/24	71,420	service luchtfilter	Uitvoeren
12/18/24	71,420	service microfilter	Uitvoeren
12/18/24	71,420	service motorolie	Uitvoeren
6/4/24	56,833	BMW/MINI service standaard omvang	Uitvoeren
6/4/24	56,833	controle niveaus	Uitvoeren
6/4/24	56,833	klein materiaal	N.v.t.
6/4/24	56,833	remvloeistof	Vervangen
6/4/24	56,833	ruitenwisserrubber vooraan	Vervangen
5/23/23	34,261	service microfilter	Uitvoeren
5/23/23	34,261	service motorolie	Uitvoeren