



CITROËN C3 SOCIÉTÉ: GC-615-LY

Vinnumber:	VF7SWYHTUMT620927	Versionname:	CITROËN C3 SOCIÉTÉ BlueHDi 100 S&S
First Registrationdate:	19/10/2021	Fiscalpower:	BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)
Expertise Mileage:	80516	Power Kw:	75
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Aluminium		
Category:	VS		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Type of climate control	Autom climate control		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Kleber: 95%	Fr.R.	Kleber: 100%
	Re.L.	Kleber: 35%	Re.R.	Kleber: 40%
Tyre profile depth FL				1.7
Tyre profile depth FR				1.1
Tyre profile depth RL				5.9
Tyre profile depth RR				5.7
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Chemical cleaning



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wheel cover RR, Deformed / Strained, Replace



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Paint



Bodywork, Not original part, Acceptable



Historique Maintenance

Immatriculation: GC-615-LY Date de 1ère immatriculation: 19/10/2021

Modèle: Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)

Date	Kilométrage	Fournisseur	Descriptif
04/02/2026	78.170	CENTRE AUTO FRANCK AUTO	TRIANGLE SUPERIEUR ARG RPLT
	0		RECYCLAGE
	0		ESSAI
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		RECHARGE CLIM
	0		AMORTISSEURS AR RPLT
	0		AMORTISSEURS AR RPLT
	0		LIQUIDE DE FREIN
	0		TRIANGLE SUPERIEUR ARD RPLT
17/10/2025	73.479	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
23/01/2025	62.187	CENTRE AUTO FRANCK AUTO	DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
10/01/2024	46.129	STELLANTIS &YOU FRANCE SAS	REVISION
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		RECYCLAGE
06/12/2023	45.620	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
19/06/2023	35.244	EUROMASTER FRANCE	REPARATION DE ROUE
01/12/2022	32.909	AZUR AUTOMOBILE	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM
19/10/2022	20.451	AZUR AUTOMOBILE	ADBLUE
05/04/2022	6.817	EUROMASTER FRANCE	REPARATION DE ROUE