



CITROËN BERLINGO: ET-920-VN

Vinnumber:	VF77BBHW6HJ895257	Versionname:	CITROËN BERLINGO BlueHDi 75 BVM Business M
First Registrationdate:	2/02/2018	Fiscalpower:	VU [3P] bvm 5-75CH-5cv (fourgonnette-)
Expertise Mileage:	57179	Power Kw:	55
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Rear parking sensors	
GPS big screen color		Seat cover lining	Lining Other
GPS storage			
GPS storage	HD		
Windows electric F			
Cruise Control			
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Kleber: 70%	Fr.R.	Kleber: 75%
	Re.L.	Kleber: 75%	Re.R.	Kleber: 75%
Tyre profile depth FL				3.8
Tyre profile depth FR				3.2
Tyre profile depth RL				3.3
Tyre profile depth RR				3.5
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 91 T
Tyre size RR				195/65 R 15 91 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			





Remote ignition key, Missing, Repair/replace (lump sum)



Remote ignition key, Broken, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Wheel cover RL, Broken, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wheel cover FR, Missing, Replace



Outside rear-view mirror base L, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Replace



Outside rear-view mirror base R, Broken, Replace



Side wall RR, Dent(s), Repair and paint (complete)



Outer sill R, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Number plate light R, Broken, Replace



Bumper R, Broken, Replace



Shutter / cover R, Missing, Replace



Roof, cabin, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: ET-920-VN Date de 1ère immatriculation: 02/02/2018

Modèle: Citroen BERLINGO BlueHDi 75 BVM Business M VU [3P] bvm 5-75CH-5cv (fourgonnette-)

Date	Kilométrage	Fournisseur	Descriptif
20/03/2026	55.467	OPEL FRANCE	REVISION
	0		LAMPE CODE AVD RPLT
	0		LAMPE RPLT
	0		BALAISSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		DIVERS CLIM
08/12/2025	51.171	STELLANTIS &YOU FRANCE SAS	LAMPE RPLT
	0		ECLAIRAGE DE PLAQUE RPLT
	0		LAMPE CODE AVD RPLT
17/01/2025	41.860	STELLANTIS &YOU FRANCE SAS	DISQUES PLAQUETTES AV RPLT
	0		BALAISSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
	0		FILTRE A AIR RPLT
	0		DIVERS CLIM
	0		REVISION
	0		PLAQUETTES AR RPLT
	0		LAMPE CODE AVD RPLT
29/08/2024	36.613	AUTO BILAN POINTE ROUGE	CONTROLE TECHNIQUE
04/01/2024	34.385	SOCIETE EXPLOITATION FRANCESCHINI	REVISION
	0		BALAISSUIE GLACE AV
	0		ADBLUE
30/09/2022	28.529	SOCIETE EXPLOITATION FRANCESCHINI	DIVERS ECHAPPEMENT
	0		RESERVOIR ADBLUE RPLT
05/09/2022	28.529	SOCIETE EXPLOITATION FRANCESCHINI	BALAISSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		ADBLUE
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		REVISION ET CLIM ET AIR ET CARBURANT

Historique Maintenance

Immatriculation: **ET-920-VN**

Date de 1ère immatriculation: **02/02/2018**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Business M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		RECYCLAGE
27/04/2022	26.172	DEKRA AUTOMOTIVE S.A	CONTRE VISITE CT
27/04/2022	26.138	SOCIETE EXPLOITATION FRANCESCHINI	ECLAIRAGE DE PLAQUE RPLT
26/04/2022	26.132	EUROMASTER FRANCE	REPLACEMENT PNEUS ETE
19/04/2022	26.012	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
06/09/2021	21.461	EUROMASTER FRANCE	REPARATION DE ROUE
24/06/2021	20.703	SOCIETE EXPLOITATION FRANCESCHINI	PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		ADBLUE
	0		FILTRE CLIM RPLT
	0		REVISION
	0		RECYCLAGE
18/09/2020	15.840	SOCIETE EXPLOITATION FRANCESCHINI	TELECHARGEMENT CALCULATEUR
12/06/2020	14.955	SOCIETE EXPLOITATION FRANCESCHINI	BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
04/02/2020	12.373	FRANCE PARE BRISE SAS	VITRE AVG RPLT
10/05/2019	6.743	PARASCANDOLA-CTO	BALAIS ESSUIE GLACE AV
	0		REVISION
16/01/2019	5.131	FRANCE PARE BRISE SAS	VITRE AVG RPLT