



Peugeot 308 (UKL): 2CDZ356

Vinnumber:	VR3FCYHZLNY540625	Versionname:	308 SW Allure 1.5 BlueHDi S&S 130pk/cv 5p
First Registrationdate:	20/06/2022	Fiscalpower:	
Expertise Mileage:	148339	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/17/91 Y			
Summer tyres:	Fr.L.	Continental: 4,3 mm	Fr.R.	Continental: 4,6 mm
	Re.L.	Continental: 3,1 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.3
Tyre profile depth FR				4.6
Tyre profile depth RL				3.1
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 91 Y
Tyre size FR				225/45 R 17 91 Y
Tyre size RL				225/45 R 17 91 Y
Tyre size RR				225/45 R 17 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Floor covering FL, Worn, Acceptable			



Seat cover FL, Stain, Cleaning



Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Grille, Broken, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Boot lid covering R, Worn, Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Roof, Dent(s) and scratch(es), Acceptable



Kenteken	2CDZ356
Merk Model	Peugeot 308 SW Allure 1.5 BlueHDi S&S 130pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/20/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/3/26	135,768	luchtfiler interieur	Vervangen
3/3/26	135,768	oliezeef	Vervangen
3/3/26	135,768	remblokken achter	Vervangen
3/3/26	135,768	richtingaanwijzer blok	Vervangen
7/14/25	112,462	120000 km	Uitvoeren
7/14/25	112,462	batterij	Vervangen
7/14/25	112,462	brandstof hoofdfilter	Vervangen
7/14/25	112,462	luchtfiler	Vervangen
7/14/25	112,462	luchtfiler interieur	Vervangen
7/14/25	112,462	oliezeef	Vervangen
7/14/25	112,462	riem of multiriem	Vervangen
7/14/25	112,462	ruitenwisserrubber achter	Vervangen
7/14/25	112,462	ruitenwisserrubber vooraan	Vervangen
11/18/24	86,823	remblokken vooraan	Vervangen
10/17/24	83,306	90000 km	Uitvoeren
10/17/24	83,306	luchtfiler interieur	Vervangen
10/17/24	83,306	oliezeef	Vervangen
10/17/24	83,306	remvloeistof	Vervangen
11/28/23	52,261	60000 km	Uitvoeren
11/28/23	52,261	brandstof hoofdfilter	Vervangen
11/28/23	52,261	luchtfiler	Vervangen
11/28/23	52,261	luchtfiler interieur	Vervangen
11/28/23	52,261	oliezeef	Vervangen
3/15/23	28,173	30000 km	Uitvoeren
3/15/23	28,173	luchtfiler interieur	Vervangen
3/15/23	28,173	oliezeef	Vervangen